



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24070331/Avh3
75 BRAS BASAH ROAD	Date:	24/09/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKP 7572E	Veh. Inspected	GBG 3194T
Policy No.	-	Coverage	0
Claim No.	MT/1287090-001	Excess	\$0.00
Assign From	RAJESWARY	Assign Date	22/07/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE	C.C	2982
Engine No.	1KD2688883	Year of Reg.	20/07/2017
Chassis No.	JTFHT02P000217057	Colour	BLACK
Odometer	205438 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15C	TRIANGLE	6
L/H Front Tyre	195R15C	TRIANGLE	6
R/H Rear Tyre	195R15C	TRIANGLE	6
L/H Rear Tyre	195R15C	TRIANGLE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/07/2024	Inspection Date	22/07/2024 (14:32)
Survey held at	KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 11 Working Days