

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	AUTO & GENERAL	INSURANCE (S) PL	Ref:	CS/AGI24070333/Enc	
	(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01		Date:	29/07/2024	
		PPING CENTRE SINGAPORE 239924	Code:	AGI	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMA 6270M	Veh. Inspected	SLG 5323G	
	Policy No.	-	Coverage	0	
	Claim No.	C10030661/CY	Excess	\$0.00	
	Assign From	-	Assign Date	22/07/2024	
2. Vehicle Details					
	Make & Model	TOYOTA COROLLA ALTIS	c.c	1598	
	Engine No.	1ZRY336756	Year of Reg.	04/10/2016	
	Chassis No.	MR053REH104559335	Colour	GREY	
	Odometer	439138 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	205/55ZR16	FARROAD	6	
	L/H Front Tyre	205/55ZR16	FARROAD	6	
	R/H Rear Tyre	205/55ZR16	FARROAD	6	
	L/H Rear Tyre	205/55ZR16	FARROAD	6	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	21/07/2024	Inspection Date	23/07/2024	
	Survey held at	TEAMWORK GARAGE PTE LTD - 53	UBI AVENUE 1 #01	-24 SINGAPORE 408934	
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days