

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III24070334/UVH3M4
Date: 13/08/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0003256_04
Claimant Vehicle No : SMZ18J Insured Vehicle No : PC8717H
Date of Loss: 09/07/2024 Nature of Claim: TP Claim No: MFL2024D0008203

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMZ18J
Make & Model: LAND ROVER RANGE ROVER SPORT, 3.0 TSS 7S SR (A) Engine No: 0880351306DT
Reg. Date: 23/12/2014 (Man. Year: 2014) Chassis No: SALWA2KE9FA506157
Colour: Black Odometer: 226388 km
Engine Capacity: 2993 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 285/35ZR22 Rear Tyre Size: 275/40R22
Front Left Side: Continental 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,701.39	5,793.93	907.46	13.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	1,150.00	560.00	32.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,411.39	6,943.93	1,467.46	17.45
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	8,411.39	5,500.00	2,911.39	34.61

INSPECTION

Date of Assignment: 22/07/2024
Date Inspected: 22/07/2024 Inspected At: SIANG HUI MOTOR WORKS
BLK 3006 UBI ROAD 1
#01-338 SINGAPORE 408700
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Aug 2024)
Parts:	M1-SUV	LAND ROVER RANGE ROVER SPORT 3.0 TSS 7S SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ18J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Warped/Cracked	5,827.77 FL	*5,600.00 FL
2	1		*REAR BOOT INNER LOCK	Serviceable	353.92 FL	*- FL
3	1		*REAR BOOT MOULDING	Cracked	668.90 FL	*480.00 FL
4	1		*REAR BOOT SIDE GARNISH	Cracked	357.70 FL	*357.70 FL
5	1		*REAR BOOT W/STRIP	Not Necessary	237.70 FL	*- FL
					Sub Total (\$\$)	7,445.99 6,437.70
					- List Item Discount on L Items 10.00/10.00% (\$\$)	744.60 643.77
					Total Parts (\$\$)	6,701.39 5,793.93

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIX REAR WINDSCREEN & TRANSFER MECHANISM	New	250.00	150.00
2	TO SPRAY PAINTING	New	680.00	500.00
3	TO REMOVE, REPLACE REAR BOOT & REPAIR END PANEL, REAR BUMPER	New	780.00	500.00
Gross Labour Cost (S\$)			1,710.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >