

祥輝汽車修理 SIANG HUI MOTOR WORKS

Blk 3006, Ubi Road 1 #01-338, Singapore 408700.
Tel: 67444605 Fax: 67440726
REG. No. 322208/00M

Date, 21/7/24

Vehicle No SMZ 18

1	IPC Rear boot	warp (cro)	\$600	\$527.77 ✓
2	IPC Rear boot inner lock	SUC		\$353.92 x
3	IPC Rear boot moulding	480 cro		\$668.90 ✓
4	IPC Rear boot side garnish	cro		\$357.70 ✓
5	IPC Rear boot w/strip	na		\$237.70 x
				\$7445.99
Less 10%				\$744.59
				\$6701.39

Labour charges: -

1	To remove & re-fix rear windscreen & transfer mechanism	\$250.00 150
2	To spray painting	\$680.00 500
3	To remove, replace rear boot & repair end panel, rear bumper	\$780.00 500
Total:		\$8411.39

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

not Authorized
LKK
mercus
22/7/24
1/5 \$5500
Hd by S.
Mephe. At. up -

P-6437-7
102
5793.93
1150
6943.53
20%
555