



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914 ATTN: HEW LEE FONG			Ref: CS/AWA24070335/Avce2(N) Date: 18/03/2025 Code: AWA	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 142M	Veh. Inspected	SLD 688C	
Policy No.	BVFCB0013842302	Coverage (\$)	0.00	
Claim No.	CSG24VFC2A00004/SG	Excess (\$)	0.00	
Assign From	HEW LEE FONG	Assign Date	22/07/2024	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E53	c.c	2999	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	WDD2130612A549455	Colour	BLACK	
Odometer	57036 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/30 R20	MICHELIN	6 mm	
L/H Front Tyre	275/30 R20	MICHELIN	6 mm	
R/H Rear Tyre	275/30 R20	MICHELIN	6 mm	
L/H Rear Tyre	275/30 R20	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/07/2024	Inspection Date	22/07/2024	
Survey held at	ADVANCE AUTO GARAGE 1 KAKI BUKIT AVENUE 6, #01-73 KAKI BUKIT AUTOBAY BLK D, SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	