

# ADVANCE AUTO GARAGE

|               |                          |        |           |
|---------------|--------------------------|--------|-----------|
| TO            | : ALLIED WOLRD ASSURANCE | DATE   | 22/7/2024 |
| VEHICLE NO    | : SLD688C (2019)         | Veron. |           |
| VEHICLE MODEL | : MERCEDES BENZ E53      |        |           |
| CHASSIS NO    | : WDD2130612A549455      |        |           |

## CLAIM DETAILS: PARTS

|                  | ITEMS                                        | QTY | UNIT PRICE  | TOTAL        |
|------------------|----------------------------------------------|-----|-------------|--------------|
| 1                | FRONT BUMPER <i>ton</i>                      | 1   | \$ 2,510.00 | \$ 2,510.00  |
| 2                | FRONT BUMPER SIDE HOLDER <i>new</i>          | 1   | \$ 165.00   | \$ 165.00    |
| 3                | FRONT BUMPER SENSOR <i>Not nec</i>           | 1   | \$ 290.00   | \$ 290.00    |
| 4                | FRONT FENDER <i>Dented</i>                   | 1   | \$ 1,285.00 | \$ 1,285.00  |
| 5                | FRONT FENDER INNER SHIELD <i>Not nec</i>     | 1   | \$ 293.00   | \$ 293.00    |
| 6                | HEADLAMP <i>Not nec</i>                      | 1   | \$ 3,989.00 | \$ 3,989.00  |
| 7                | FRONT DOOR <i>Repair</i>                     | 1   | \$ 2,959.00 | \$ 2,959.00  |
| 8                | FRONT DOOR WEATHERSTRIPE <i>new</i>          | 1   | \$ 269.00   | \$ 269.00    |
| 9                | FRONT DOOR OUTER HANDLE <i>new</i>           | 2   | \$ 221.00   | \$ 221.00    |
| 10               | FRONT DOOR WING MIRROR <i>new</i>            | 1   | \$ 1,405.00 | \$ 1,405.00  |
| 11               | FRONT DOOR WING MIRROR COVER <i>ut</i>       | 1   | \$ 121.00   | \$ 121.00    |
| 12               | FRONT DOOR WING MIRROR SIGNAL LAMP <i>ut</i> | 1   | \$ 141.00   | \$ 141.00    |
| 13               | FRONT DOOR WING MIRROR GLASS <i>new</i>      | 1   | \$ 689.00   | \$ 689.00    |
| 14               | REAR DOOR <i>Dented</i>                      | 1   | \$ 2,893.00 | \$ 2,893.00  |
| 15               | REAR DOOR WEATHERSTRIPE <i>new</i>           | 1   | \$ 287.00   | \$ 287.00    |
| 16               | REAR DOOR OUTER HANDLE <i>Damaged</i>        | 1   | \$ 240.00   | \$ 240.00    |
| 17               | REAR BUMPER <i>new</i>                       | 1   | \$ 2,799.00 | \$ 2,799.00  |
| 18               | REAR BUMPER SIDE HOLDER <i>new</i>           | 1   | \$ 157.00   | \$ 157.00    |
| 19               | REAR BUMPER SENSOR <i>new</i>                | 1   | \$ 295.00   | \$ 295.00    |
| 20               | REAR BUMPER REFLECTOR <i>new</i>             | 1   | \$ 98.00    | \$ 98.00     |
| 21               | TAILLAMP <i>new</i>                          | 1   | \$ 1,188.00 | \$ 1,188.00  |
| TOTAL PRICE:     |                                              |     |             | \$ 22,294.00 |
| LESS 10%:        |                                              |     |             | \$ 2,229.40  |
| SUB TOTAL PRICE: |                                              |     |             | \$ 20,064.60 |

10781  
9702.90

## SPECIAL NETT ITEMS

|        | ITEMS                                          | QTY   | UNIT PRICE  | TOTAL       |
|--------|------------------------------------------------|-------|-------------|-------------|
| 1      | FRONT BUMPER CLIPS <i>Nec</i>                  | 1 SET | \$ 50.00    | \$ 50.00    |
| 2      | FRONT FENDER INNER SHIELD CLIPS <i>Not nec</i> | 1 SET | \$ 30.00    | \$ 30.00    |
| 3      | FRONT WHEEL RIM <i>3x1</i>                     | 1     | \$ 1,500.00 | \$ 1,500.00 |
| 4      | FRONT TYRE <i>3x1</i>                          | 1     | \$ 350.00   | \$ 350.00   |
| 5      | REAR BUMPER CLIPS <i>new</i>                   | 1 SET | \$ 50.00    | \$ 50.00    |
| TOTAL: |                                                |       |             | \$ 1,980.00 |

100

| LABOUR |                                        | PRICE                  | ADJUSTED COST | APPROVED |
|--------|----------------------------------------|------------------------|---------------|----------|
|        | JOB                                    |                        |               |          |
| 1      | PANEL BEATING, REMOVE AND REFIT PARTS  | \$ <del>1,400.00</del> | 800           |          |
| 2      | SPRAY PAINTING TO AFFECTED AREA        | \$ 1,400.00            | 1000          |          |
| 3      | WIRING CHECK                           | \$ <del>100.00</del>   | 30            |          |
| 4      | TO APPLY TUFF COAT                     | \$ <del>150.00</del>   | 30            |          |
| 5      | TO REMOVE FRONT BUMPER SENSOR          | \$ <del>100.00</del>   | 50            |          |
| 6      | TO TRANSFER FRONT & REAR DOOR FITTINGS | \$ <del>200.00</del>   | 60            |          |
| 7      | TO REMOVE REAR BUMPER SENSOR           | \$ <del>100.00</del>   | 50            |          |
| 8      | TO PERFORM WHEEL ALIGNMENT             | \$ 150.00              | X             |          |
| 9      | TO PERFORM DIAGNOSTIC TEST             | \$ 250.00              | X             |          |
| TOTAL: |                                        | \$ 3,950.00            |               |          |

2020

# ESTIMATE REPORT

TOTAL PARTS COST: \$ 22,044.60

TOTAL LABOUR COST: \$ 3,950.00

TOTAL REPAIR COST: \$ 25,994.60

total: 11822.90

L/S: 9.4K

07 Days

9,400

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: