



Mercedes-Benz

ESTIMATE FOR SMR5310Z

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#22-00
SINGAPORE 048580
63476100

Vehicle & Document Information

WIP No 19506
Reg No/Reg Date SMR5310Z / 13/01/2020
Date In/Mileage / 0
Chassis No WDD1771872J1572089
Engine No 28291480270087
Make/Model MB/A 200
Colour/Trim 021 149 polar white/ 041 101 ARTICO Blac

Account No WI000576 Terms Credit Date/Time Printed 01/08/2024/ 10:18 CSE K0 Operator 301 / Kerlyn Ong

Description of Goods / Services

Qty Unit Price Disc% Amount

Z REQUEST

Customer Request

M BPNSUN

POLICY NO/ACC DATE : 2000002069-04 // 17/07/2024

DRIVE IN/TP VEHICLE NO. : 18/07/2024 // YR317X - III

DATE IN/DATE SURVEY:

DIRECT SETTLEMENT : 31/7/2024 // LKK - Hsiao Tong

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESPRAY BOOT LID & REAR BUMPER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

M BPNSUN

SUNDRY

M TRUNK LID

M MERCEDES STAR

M GROMMET

M A200 MODEL PLATE

M REAR BUMPER

M REAR BUMPER LOWER TRIM

M CTR/ REAR BUMPER LOWER CHROME

M REAR SWITCH MODULE

M COUPLING HOUSING

M REAR BUMPER HOLDER

M CTR/ BASIC CARRIER FOR BUMPER

M REAR CROSS MEMBER

2880 2880.00
- 1600 1800.00
0.10 380.00
- 120.00
- 15.00
1.00 2981.87 00.00 2981.87
1.00 66.44 00.00 66.44
3.00 3.11 00.00 9.33
1.00 153.42 00.00 153.42
1.00 1520.51 00.00 1520.51
1.00 555.27 00.00 555.27
1.00 326.70 00.00 326.70
1.00 184.33 00.00 184.33
1.00 15.64 00.00 15.64
1.00 100.62 00.00 100.62
1.00 192.13 00.00 192.13
1.00 563.81 00.00 563.81

Confirmed & accepted by

Kerlyn Ong Kai Li

DID: 6771 4420 HP: 9186 5113

Email: kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Nett 11,865.07
9% GST on 11865.07 1067.86

Total Payable 12,932.93

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Authorized signatory and company stamp
- Parts prices are subject to confirmation

This is a computer generated document, no signature is required.
Estimate is quoted excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Acknowledged by Repairer

Signature:

Date:

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG