

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

Vehicle Number : GV6444P
Vehicle Model : TOYOTA HIACE
Accident Date : 19.07.2024
Original Reg Date : 29.08.2022

Date : 24.07.2024
Chassis : TRH2000345700

Xiao Tony

ESTIMATE

1	1 pc	Rear Bumper		605.80	+
2	1 pc	Rear Bumper Side Retainers	92.60	185.20	+
3	1 set	Rear Bumper Clips		50.00	+
4	1 set	Tyre case		350.00	100(SN)
5	1 pc	Rear floor panel (Rear Portion)		1,148.50	+
6	1 pc	Rear fender LH		1,958.60	✓
7	1 pc	Rear INNER fender LH		1,685.20	+
8	1 pc	Rear fender mudflap LH		85.60	✓
9	1 pc	Rear fender air duct		105.70	+
10	1 pc	Rear fender inner cover		98.70	+
11	1 pc	Rear fender inner trim		356.80	+
12	1 pc	Rear fender side door railing		648.70	+
13	1 pc	Rear Absorber		325.90	+
14	1 pc	Rear wheel hub bearing		298.20	+
15	1 pc	Rear leaf spring bracket	185.60	371.20	+
16	1 pc	Rear leaf spring LH		1,394.50	+

SUBTOTAL 9,668.60
Less 25% 2,417.15
TOTAL 7,251.45

S-X: 100
1204420
1533.15

Special Nett

1	1 set	Body Panel Joint Sealant		120.00	60
2	1 set	Floor panel vinyl mat		450.00	+
3	1 pc	Tyre		250.00	+
4	1 set	Rear Floor panel wooden board		600.00	+

60

Labour charge

Panel Beating	1,400.00	4w
Spray painting	1,400.00	250
Anti rust	200.00	* 40 X
Remove and install wooden board	200.00	+
4 Wheel Aightment	120.00	80

Ag...
H/O...

Remove rear undercarriage		300.00	x
Repair and realigh chassis member		350.00	+
To apply undercoat and sealant to affected area		280.00	+
Check Wiring on tailamps		120.00	30

760

Total 13,041.45

Adrian L

1/s 24/07/24

042p

Total: 2453.15

2/s 1.91c

1.91c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: