

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 19 Aug 2024

Preliminary Advice

Vehicle No	: YP1243D	Accident Date	: 19/07/2024
Make	: MITSUBISHI CANTER	Policy No.	: MCF24B00000200
Assignment Date	: 22/07/2024	Excess	: S\$600.00
Date of Inspection	: 23/07/2024	Est. Duration of Repair	: 7
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,156.50 (inclusive supp \$511.50)
Revised Amount	:S\$	8,691.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,691.00
 Lump Sum Repair	 :S\$	 6,950.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	30,000.00
COE / PARF Rebate	:S\$	7,139.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,861.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Kindly approve on supplementary.