

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 23 Jul 2024

**Preliminary Advice**

Vehicle No	: YP1243D	Accident Date	: 19/07/2024
Make	: MITSUBISHI CANTER	Policy No.	: MCF24B00000200
Assignment Date	: 22/07/2024	Excess	: S\$600.00
Date of Inspection	: 23/07/2024	Est. Duration of Repair	: 7
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,645.00
Revised Amount	:S\$	6,019.50
Check Items (Estimated)	:S\$	5,249.50
Total	:S\$	11,269.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	30,000.00
COE / PARF Rebate	:S\$	7,139.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,861.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : The vehicle repair on lump sum basis.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.