



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/ECICS
Policy No:	MCF24B00000200	Date of Loss:	19/07/2024
Vehicle Reg. No.:	YP1243D	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TSG FOOD PTE LTD		
Driver:	DIAO YUELI		
Make/Model:	MITSUBISHI CANTER, 3.0 D FEB21 (M)	Vehicle Reg. Date:	02/02/2016
Vehicle Colour:	WHITE		
Engine No:	4P10B98069	Chassis No:	FEB21CA20001
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT		
Remarks:	VEHICLE TOW INTO WOODLANDS WORKSHOP ON 19/07/2024		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

*Not Authorized
L1 Rep @ 6950/-
Returning After Repair
Ex @ 600/-
Today*

COST OF CLAIMS

	Amount
Parts	8,965.00
Miscellaneous Items	280.00
Labour	2,400.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	11,645.00
+ GST 9.00% (\$\$)	1,048.05
Nett Amount (\$\$)	12,693.05

This claim is handled by: DORLYN LI YAZHU

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

YP1243D
00 IECS

Reference

Part Source: (Last Synchronised: 22 Jul 2024)

Parts: N/A MITSUBISHI CANTER 3.0 D FEB21 (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/YP1243D/22/07/2024 17:04

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc front LH side mirror stay	0.00	0.00	R *190.00 F
2	1		*1 pc front LH side mirror round	0.00	0.00	CM *35.00 F
3	1		*1 pc front LH side mirror square	0.00	0.00	CM *60.00 F
4	1		*1 pc front LH side mirror stay top garnish	0.00	0.00	CM *30.00 F
5	1		*1 pc front LH side cornal panel	0.00	0.00	CM *250.00 F
6	1		*1 pc LH headlamp	0.00	0.00	CM *260.00 F
7	1		*1 pc LH signal lamp	0.00	0.00	Bu *120.00 F
8	1		*1 pc LH side reflector	0.00	0.00	CM *110.00 F
9	1		*1 pc front bumper LH side pad	0.00	0.00	CM *160.00 F
10	1		*1 pc front bumper RH side pad	0.00	0.00	CM *160.00 F
11	1		*1 pc RH headlamp	0.00	0.00	split *240.00 F
12	1		*1 pc RH signal lamp	0.00	0.00	CM *240.00 F
13	1		*1 pc front bumper	0.00	0.00	Bu *380.00 F
14	1		*1 pc front RH cornal panel	0.00	0.00	CM *250.00 F
15	1		*1 pc front RH side mirror	0.00	0.00	DIY *60.00 F
16	1		*1 pc front LH door light	0.00	0.00	CM *40.00 F
17	1		*1 pc front RH tyre rim	0.00	0.00	DIY *280.00 F
18	1		*1 pc front RH top arm	0.00	0.00	DIY *1,800.00 F
19	1		*1 pc front RH lower arm	0.00	0.00	Bu *1,300.00 F
20	1		*1 pc front RH knuckle arm	0.00	0.00	Bu *1,300.00 F
21	1		*1 pc front RH bearing	0.00	0.00	Bu *40.00 F
22	1		*1 pc radiator fan cowling	0.00	0.00	CM *220.00 F
23	1		*1 pc radiator fan blade	0.00	0.00	Bu *105.00 F
24	1		*1 pc power steering oil spare tank	0.00	0.00	CM *520.00 F

F=Franchise part.

Sub Total (\$\$) 8,150.00

+ Margin on L,N Items 10.00% (\$\$) 815.00

Total Parts (\$\$) 8,965.00

Cheng Hoe Motor Pte Ltd/YP1243D/22/07/2024 17:04. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 pc front RH tyre	280.00

Miscellaneous Items

1 1 1 pc front RH tyre

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total (\$\$) 280.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Towing (by owner)	New	75.00
2	Remove & refix frt bumper assy, grille, headlamps, side mirrors; to straighten, knocking & repair front LH windscreen pillar, repair frt both doors, frt LH floorboard panel & realign cabin position	New	900.00
3	Remove & refix dashboard, meter assy & check wiring	New	180.00
4	Putty & respray on frt bumper, both cornal panel, frt LH windscreen pillar, frt both door	New	800.00
5	Remove & refix frt RH undercarriage, check steering & wheel alignment	New	350.00
Gross Labour Cost (S\$)			2,400.00

Cheng Hoe Motor Pte Ltd/YP1243D/22/07/2024 17:04. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source:

(Last Synchronised: 29 Jul 2024)

Parts: N/A

MITSUBISHI CANTER 3.0 D FEB21 (M) (Model not available in database)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YP1243D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Attn Kenneth Kong

YP1243D
0D/ECICS
Supplementary

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc front LH door inner lock			
2	1		*1 pc front bumper LH bracket	0.00	0.00	*260.00 F
3	1		*1 pc room mirror	0.00	0.00	*110.00 F
				0.00	0.00	*95.00 F
Sub Total (\$\$)						465.00
+ Margin on L,N Items 10.00% (\$\$)						46.50
Total Parts (\$\$)						511.50

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >