

# REPAIR DETAILS

Attn Kenneth Kong

YP1243D  
ODIECICS  
Supplementary

## Reference

**Part Source:** (Last Synchronised: 29 Jul 2024)  
**Parts:** N/A MITSUBISHI CANTER 3.0 D FEB21 (M) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for YP1243D)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc front LH door inner lock	0.00	0.00	172 *260.00 F ✓
2	1		*1 pc front bumper LH bracket	0.00	0.00	112 *110.00 F ✓
3	1		*1 pc room mirror	0.00	0.00	112 *95.00 F ✓
Sub Total (\$\$)						465.00
+ Margin on L,N Items 10.00% (\$\$)						46.50
Total Parts (\$\$)						511.50

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

There are no labour items selected.

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >