

WHEELZ 4 YOU

not Authorised
new car
23/7/24
2/5 @ 4100
5 days

To: Motor Claims Department

Vehicle No: SMP5380G

Model: TOYOTA SIENTA

Date: 18/07/2024

Estimated Repair Cost For SMP5380G TOYOTA SIENTA

QTY	Parts	Amount
1	Rear bumper <i>2e/ Tofa</i>	\$ 994.37 ✓
2	Rear bumper side retainer @ \$125.64 <i>11</i>	\$ 251.28 X
2	Rear bumper reflector @ \$99.84 <i>11</i>	\$ 199.68 X
1	Rear bumper top garnish <i>De</i>	\$ 383.94 ✓
2	Rear bumper side garnish @ \$298.31 <i>11</i>	\$ 596.62 X
1	Rear bumper lamp <i>Che</i>	\$ 245.63 ✓
1	Tailgate <i>23/24</i>	\$ 1,991.51 ✓
1	Tailgate lock <i>Dongle</i>	\$ 453.52 ✓
1	Tailgate rubber <i>8e</i>	\$ 395.84 X
1	Tailgate logo <i>1e1</i>	\$ 104.21 ✓
1	Tailgate outer garnish <i>11</i>	\$ 454.39 X
1	Tailgate trimboard <i>11</i>	\$ 385.05 X
2	tailgate lamp @ \$569.14 <i>11</i>	\$ 1,138.28 X
1	Tailgate Sienta emblem <i>1e1</i>	\$ 109.31 ✓
1	Tailgate V emblem <i>1e1</i>	\$ 89.28 ✓
1	Tailgate glass moulding <i>1e1</i>	\$ 181.21 ✓
2	Rear number plate lamp @ \$48.15 <i>11</i>	\$ 96.30 X
2	Taillamp @ \$787.55 <i>11</i>	\$ 1,575.10 X
1	Rear end panel garnish <i>7e1</i>	\$ 133.92 ✓
1	Rear end panel inner <i>12</i>	\$ 1,685.00 X
1	Rear end panel outer <i>23/24</i>	\$ 846.23 ✓
1	Rear compartment tray <i>11</i>	\$ 411.84 X
1	Rear compartment board <i>11</i>	\$ 586.21 X
1	Rear floor panel <i>11</i>	\$ 1,216.34 X
2	Rear fender inner trim @ \$999.85 <i>11</i>	\$ 1,999.70 X
Parts Sum:		\$ 16,524.76
Parts Less 25% :		\$ 4,131.19
Parts Total:		\$ 12,393.57

Special Nett Items

1	Tailgate glass sealant <i>1e1</i>	\$ 60.00 40 5/2
1	Tailgate glass inner seal <i>1e1</i>	\$ 60.00 20 "
1	Tailgate sealant <i>11</i>	\$ 100.00 X
1	Reverse sensor <i>Che</i>	\$ 280.00 200 "
1	Reverse camera <i>11</i>	\$ 450.00 X
1	Rear number plate <i>11</i>	\$ 80.00 X
1	Rear bumper clips <i>1e1</i>	\$ 50.00 30 "
1	Rear bumper rivets <i>11</i>	\$ 50.00 X
1	Tailgate trim board clip <i>11</i>	\$ 80.00 X

Special Nett Items Total: \$ 1,210.00

Labour & Misc Charges

Description	Amount
To Check Wiring	\$ 50.00 30
RNR inner trims and garnishes	\$ 150.00 60
To Install Reverse Sensor	\$ 80.00 40
To transfer tailgate parts	\$ 150.00 65
To transfer tailgate glass	\$ 150.00 120
To repair exhaust	\$ 180.00 X
To install reverse camera	\$ 150.00 X
To apply Body Sealant On Body Joints	\$ 120.00 X
Anti-rust	\$ 120.00 50
Labour to remove necc parts, cut and reweld panel, repair chasiss	\$ 1,200.00 600
Spray painting	\$ 1,200.00 700
Labour Charges Total:	\$ 3,550.00

Parts Total: \$ 12,393.57
Special Nett Items Total: \$ 1,710.00
Labour Charges Total: \$ 3,550.00
Total Cost Of Repair: \$ 17,653.57
(Non-Inclusive of GST)

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

2 4238.07
 252
 3178.55
 290
 1660
 5.08.55
 202
 4102.