



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24070342/Aqh3m4
75 BRAS BASAH ROAD	Date:	17/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLA 7120T	Veh. Inspected	SMM 3525K
Policy No.	-	Coverage	0
Claim No.	MT/1287103-002	Excess	\$0.00
Assign From	HELENA TAN	Assign Date	23/07/2024

2. Vehicle Details

Make & Model	TOYOTA NOAH HYBRID	C.C	1797
Engine No.	2ZR0D59537	Year of Reg.	26/06/2019
Chassis No.	ZWR800385029	Colour	BLACK
Odometer	99828 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/50R17	DUNLOP	6
L/H Front Tyre	215/50R17	DUNLOP	6
R/H Rear Tyre	215/50R17	DUNLOP	6
L/H Rear Tyre	215/50R17	DUNLOP	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/07/2024	Inspection Date	23/07/2024 (15:15)
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a.	Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	

5b.	Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days	