

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LEE MAN HON
 BLK 241 BUKIT PANJANG RING RD #07-145
 SINGAPORE 670241

Contact : 96691813

TP NC
 Xiao Chun.

TAX INVOICE

Repair Code : CLM18315

Date in : 22/07/2024

Vehicle Num. : SMM3525K

Model : TOYOTA NOAH HYBRID 7-SEATER 1.8X CVT

Chassis/Eng# : ZWR800385029/2ZR0D59537

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR AXLE <i>new</i>	1	3516.80	+ 3,516.80
REAR BUMPER <i>Dehnd</i>	1	810.20	✓ 810.20
REAR BUMPER RH REFLECTOR <i>new</i>	1	81.80	✓ 81.80
REAR BUMPER SIDE RETAINER L/R <i>RH cancelled</i>	2	109.60	109.60 219.20
REAR RH DOOR <i>Revs</i>	1	2711.40	+ 2,711.40
REAR RH FENDER <i>Dehnd</i>	1	2012.00	✓ 2,012.00
REAR RH FENDER INNER SHIELD <i>Dehnd</i>	1	371.70	✓ 371.70
REAR RH FENDER WINDOW GLASS WITH MOULDING <i>new</i>	1	1268.20	+ 1,268.20
REAR RH SHOCK ABSORBER <i>new</i>	1	162.50	+ 162.50
REAR RH TAILLAMP LOWER GARNISH <i>Dehnd</i>	1	283.90	✓ 283.90
REAR RH TAILLAMP LOWER GARNISH SIDE BRACKET <i>cancelled</i>	1	240.40	+ 240.40
REAR RH WHEEL BEARING <i>new</i>	1	1228.80	+ 1,228.80
Subtotal before discount			12,906.90
Percentage discount 25%			3,226.73
Sub-total 1			9,680.18
FRONT RADIO SET <i>Dehnd</i>	1	2000.00	180 2,000.00
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	30 80.00
REAR RH 215/50R17 TYRE <i>new</i>	1	500.00	+ 500.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

LEE MAN HON
 BLK 241 BUKIT PANJANG RING RD #07-145
 SINGAPORE 670241

Contact : 96691813

TAX INVOICE

Repair Code : CLM18315

Date in : 22/07/2024

Vehicle Num. : SMM3525K

Model : TOYOTA NOAH HYBRID 7-SEATER 1.8X CVT

Chassis/Eng# : ZWR800385029/2ZR0D59537

REAR RH FENDER INNER SHIELD CLIPS - SET	1	50.00	+	50.00
REAR RH FENDER WINDOW GLASS SEALANT	1	80.00	+	80.00
REAR RH SPORT RIM	1	980.00	500	980.00
REAR RH TAILLAMP LOWER GARNISH CLIPS - SET	1	50.00	20	50.00
Subtotal before discount				3,740.00
Percentage discount 0%				0.00
Sub-total 2				3,740.00
Parts-total				13,420.18

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall fender glass

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knucke arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

3,080.00

16,500.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*** This is a computer-generated document which requires no signature.***

page 2

Adrian C
 N/S 23/07/24

No of days 08

total 4695.67
 N/S: 37K ✓