

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

22-Jul-24

Steve (LKK)

23/7/24, 10.30am

in R

L/S, 4 dys

My Al sy

ESTIMATE REPAIR BILL FOR TOYOTA PREVIA REGN NO: SMT/403 L

1 pc	Front o/s fender / M	\$	1,549.12	725 ✓
1 pc	Front o/s fender garnish X R	\$	280.60	
1 pc	Front o/s fender inner shield X M	\$	235.80	
1 pc	Front o/s door / M	\$	2,655.90	1732 ✓
1 pc	Front o/s door chrome moulding X R	\$	245.00	
1 pc	Rear o/s door X M R	\$	2,856.80	
1 pc	Rear o/s door chrome moulding X M	\$	245.00	
		\$	8,068.22	2457
	Less 25%	\$	2,017.05	-25%
		\$	6,051.17	1842.75

S/NETT

1 set	Front o/s fender inner shield clips	\$	70.00	X
	Sundry	\$	50.00	X
	To check wheel alignment	\$	80.00	X
	To dismantle and refit the inner component of Front o/s door to new shell door	\$	150.00	50
	To dismantle and refit the inner component of rear o/s door to new shell door	\$	150.00	X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust the same etc	\$	600.00	/
	To putty and spray painting on front o/s fender, front o/s door, rear o/s door	\$	1,050.00	800
	To apply rustproofing on the repaired and replaced panels.	\$	250.00	30
		\$	8,451.17	1480

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(TS ARE SUBJECTED TO GST)

COST OF REPAIR DO NOT INCLUDE
GES.

3322.75

L/S - 2658.20
= 2650