



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24070344/Avh3
75 BRAS BASAH ROAD	Date:	16/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLW 9964X	Veh. Inspected	GBK 900X
Policy No.	-	Coverage	0
Claim No.	MT/1287245-003	Excess	\$0.00
Assign From	AMANDA CHOOI	Assign Date	23/07/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE DX	C.C	2754
Engine No.	1GD8473790	Year of Reg.	24/12/2019
Chassis No.	GDH2011031411	Colour	SILVER
Odometer	109361 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195 R15C	MICHELIN	6
L/H Front Tyre	195 R15C	MICHELIN	6
R/H Rear Tyre	195 R15C	MICHELIN	6
L/H Rear Tyre	195 R15C	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/07/2024	Inspection Date	23/07/2024 (15:26)
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 13 Working Days