



**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**







**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**





**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**





**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**




**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**






**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**





**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**





**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**





**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**





**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**





**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**






**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**





**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**






**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**





**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**



**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**







**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**




**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**





**PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 20 of 20)

### PHOTOGRAPHS FOR VEHICLE NO. : GBK 900X

