

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LIM CHEE KEONG
984D BUANGKOK LINK #08-33
SINGAPORE 537984

Contact : 90708078

TPINC
Xiao Chuan

TAX INVOICE

Repair Code : CLM16369

Date in : 22/07/2024

Vehicle Num. : SJU87X

Model : INFINITI Q50 2.0T A/T (R18) EU6

Chassis/Eng# : JN1BCAV37Z0480683/274AE035899A

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Devised</i>	1	1247.90	✓ 1,247.90
REAR BOOTLID 'LOGO' EMBLEM	1	72.20	✓ 72.20
REAR BOOTLID 'Q50' EMBLEM	1	122.40	✓ 122.40
REAR BOOTLID DAMPER L/R <i>new</i>	2	219.90	+ 439.80
REAR BOOTLID HINGES L/R <i>new</i>	2	66.00	+ 132.00
REAR BOOTLID INNER RUBBER STOPPER L/R <i>new</i>	4	15.00	+ 60.00
REAR BOOTLID INNER TRIM GARNISH <i>new</i>	1	412.60	+ 412.60
REAR BOOTLID LOCK STRIKER <i>new</i>	1	70.80	+ 70.80
REAR BOOTLID MECHANISM LOCK <i>Devised</i>	1	198.60	✓ 198.60
REAR BOOTLID NUMBER PLATE LAMP L/R <i>new</i>	2	67.20	+ 134.40
REAR BOOTLID OPENER SWITCH <i>new</i>	1	98.50	+ 98.50
REAR BOOTLID OUTER LOWER CHROME GARNISH <i>new</i>	1	180.10	+ 180.10
REAR BOOTLID OUTER TOP CHROME GARNISH <i>Emberd</i>	1	689.50	520 ✓ 689.50
REAR BOOTLID REFLECTOR L/R <i>RT emberd</i>	2	497.70	497.70 995.40
REAR BOOTLID REVERSE CAMERA <i>new</i>	1	1377.90	+ 1,377.90
REAR BOOTLID WEATHER STRIP <i>new</i>	1	167.10	✓ 167.10
REAR BUMPER <i>Devised</i>	1	1039.30	✓ 1,039.30
REAR BUMPER REFLECTOR L/R <i>new</i>	2	68.90	+ 137.80

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LIM CHEE KEONG
984D BUANGKOK LINK #08-33
SINGAPORE 537984

Contact : 90708078

TAX INVOICE

Repair Code : CLM16369

Date in : 22/07/2024

Vehicle Num. : SJU87X

Model : INFINITI Q50 2.0T A/T (R18) EU6

Chassis/Eng# : JN1BCAV37Z0480683/274AE035899A

REAR BUMPER REINFORCEMENT	Decker	1	904.60	712	904.60
REAR BUMPER REINFORCEMENT BRACKET L/R	new	2	157.10	+	314.20
REAR BUMPER REVERSE SENSOR	2 pieces d	4	258.20	516.40	1,032.80
REAR BUMPER REVERSE SENSOR 'O' RING	2 pieces new	4	15.00	30	60.00
REAR BUMPER REVERSE SENSOR HOLDER	new	4	53.20	✓	212.80
REAR BUMPER SIDE RETAINER L/R	new	2	43.30	+	86.60
REAR BUMPER TOW HOOK COVER	Decker	1	40.80	✓	40.80
REAR END PANEL	Decker	1	836.20	✓	836.20
REAR END PANEL ANTENNA SENSOR	center	1	97.30	✓	97.30
REAR END PANEL INNER TOP GARNISH	Decker	1	76.70	✓	76.70
REAR EXHAUST GASKET	3 new	1	19.70	+	19.70
REAR EXHAUST MOUNTING	new	1	115.10	+	115.10
REAR EXHAUST SILENCER BOX	Repair (Best)	1	1245.00	10gal / Repair (200)	1,245.00
REAR TAILLAMP L/R	new	2	1104.30	+	2,208.60
REAR TAILLAMP PANEL L/R	new	2	563.40	+	1,126.80

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LIM CHEE KEONG
984D BUANGKOK LINK #08-33
SINGAPORE 537984

Contact : 90708078

TAX INVOICE

Repair Code : CLM16369

Date in : 22/07/2024

Vehicle Num. : SJU87X

Model : INFINITI Q50 2.0T A/T (R18) EU6

Chassis/Eng# : JN1BCAV37Z0480683/274AE035899A

Subtotal before discount		6387.40	15,953.50
Percentage discount 10%		5748.66	1,595.35
Sub-total 1		S.N.20	14,358.15
REAR BOOTLID INNER TRIM GARNISH CLIPS - SET	1	50.00	50.00
REAR BOOTLID NUMBER PLATE	1	25.00	25.00
REAR BOOTLID NUMBER PLATE HOLDER	1	50.00	50.00
REAR BUMPER CLIPS - SET	1	50.00	50.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	30.00
Subtotal before discount			205.00
Percentage discount 0%			0.00
Sub-total 2			205.00
Parts-total			14,563.15

LABOUR

To transfer rear bootlid mechanism lock outer handle reflector

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

2,320.00

16,883.15

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s)
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

page 3

Attn: Cy
L/S 23/07/24.

No 08 L/S 016

Total: 7498.66
A/S: 6K

6K