

(08/11/13) • wef

ASS. REC. BY: Marcus

REF:

CD/11124070347/11193

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.


L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Rear 6 mm
R/Bal. 6 mm
L/Bal. 6 mm
D.O.I. 24/7/24

30/7/24 4/5 @ 3200 informed Alex

CARSMITH PRIVATE LIMITED
PREMIER@8 KAKI BUKIT AVE 4 #04-35 Singapore 415875
Tel: 9091 0000

Not Authorized
 du
 moran/
 24/7/24
 1/5 \$ 3200
 Telephoto Helioph-
 Helioph

VEHICLE NO: SLL1327X
 MAKE & MODEL: HONDA VEZEL
 DOA: 19.07.2024
 CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS	
REAR BUMPER	1	\$ 1,654.00	20/20	566.10
REAR BUMPER RETAINER RH nly	1	\$ 98.00	11 X	
REAR BUMPER REFLECTOR RH nly	1	\$ 325.00	11 X	
REAR END PANEL	1	\$ 952.50	R X	
REAR END PANEL STRIKER	1	\$ 58.50	11 X	
REAR END PANEL LINING	1	\$ 102.00	11 X	
TAILGATE	1	\$ 1,995.50	20/20	1099.20
TAILGATE LOCK Tail lamp nly	1	\$ 495.50	CRG	480.60
TAILGATE LAMP RH nly	1	\$ 552.00	SCR	280.60
TAILGATE ABSORBER	2	\$ 247.00	11 X	
TAILGATE LOGO	1	\$ 108.00	SCR X	
TAILGATE WEATHERSTRIP	1	\$ 295.00	11 X	
TAILGATE INNER BOARD	1	\$ 855.00	Re/tern	281.30
TAILGATE INNER PULL POCKET	1	\$ 108.60	11 X	
TAILGATE CENTRE CHROME	1	\$ 225.00	11 X	
TAILGATE TRIMBOARD Top	1	\$ 158.70	11 X	
TAILGATE HINGE	2	\$ 199.00	11 X	
REAR BUMPER SIDE LH	1	\$ 280.40	20/woped	
TOOL SPONGE	1	\$ 256.00	11 X	
REAR FENDER LH	1	\$ 1,451.00	11 X	
REAR FENDER WHEEL ARCH LH	1	\$ 389.00	Top	280.60
REAR FENDER INNER SHIELD LH	1	\$ 325.00	11 X	
		\$ 11,130.70		
	LESS 20%	\$ 2,322.26		
	SUB TOTAL	\$ 9,289.04		

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR NUMBER PLATE w. nly screen soaked	1 SET	\$ 90.00	CRG S/N
REAR BUMPER CLIP	1 SET	\$ 50.00	11 X
REAR END PANEL TOP GARNISH CLIP	1 SET	\$ 50.00	11 X
REVERSE SENSOR	1 SET	\$ 480.00	SCR X
REAR BUMPER REFLECTOR RH	1	\$ 151.00	11 X
TAILGATE TRIMBOARD CLIPS	1 SET	\$ 60.00	11 X 30
	SUB TOTAL	\$ 881.00	

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK REAR WIRING AND LIGHTING SYSTEM	1	\$ 150.00	20
REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 150.00	30

REMOVE AND REFIT REAR WINDSCREEN	1	\$ 200.00	120
REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	1	\$ 150.00	11 X
PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,300.00	550
SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,300.00	520
APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	30

SUB TOTAL \$ 3,350.00

GRAND TOTAL \$ 13,520.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-3268.80
 200
 2615.04
 120
 1270
 4025.04
 217
 3204