

Not Authoited
61Rnp \$ 3450/-

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9598S

AAD2405-031

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

22 JUL 2024

SHD9598S

JTDKB3FU503079484

200303878K

TOYOTA

PRIUS

5/5/2024

SNM5006S/ China-

22/3/2019

PART	LIST
1 COVER, FRONT BUMPER	\$ Bu 516.00 ✓
1 COVER, FRONT BUMPER HOLE, RH	\$ Pu 37.07 X
1 ABSORBER, FRONT BUMPER ENERGY	\$ Pu 100.17 X
1 ABSORBER, FRONT BUMPER, LOWER	\$ Pu 167.37 X
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$ R 902.16 X
1 REINFORCEMENT, FRONT BUMPER, NO.2	\$ R 309.96 X
1 FRONT BUMPER SIDE RETAINER RH	\$ Dis 80.10 ✓
1 JAR ASSY, WINDSHIELD WASHER	\$ Rd 219.10 ✓
1 UNIT ASSY, HEADLAMP, RH	\$ m3cm 2,637.60 ✓
1 LAMP ASSY, FOG, RH	\$ Pu 1,200.78 X
1 WHEEL, DISC	\$ Su 2,554.70 X
1 FENDER SUB-ASSY, FRONT RH	\$ R 977.80 ✓
1 LINER, FRONT FENDER, RH	\$ Pu 206.70 X
1 FRONT FENDER EMBLEM RH	\$ ne 54.60 ✓

TOTAL	\$	9,964.11
25%	\$	2,491.03
	\$	7,473.08

Special Nett

1 FRT BUMPER CLIP	\$	ne 65.00 603AL
1 FRT BUMPER SIDE RETAINER CLIP	\$	nn 65.00 X
1 FENDER LINER CLIP	\$	nn 75.00 X
TOTAL	\$	205.00

Trans-cab Auto Services Pte Ltd**AAD2405-031**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9598S

TOTAL PARTS	\$	7,678.08
--------------------	-----------	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	301
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	4901
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	2d
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	4001
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of front fender panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X

TOTAL	\$	4,990.00
--------------	-----------	-----------------

Over All Total	\$	12,668.08
-----------------------	-----------	------------------

(Lump Sum) Repair Days~~04 Days~~

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: