



ZOOM AUTOWERKS PTE LTD

LKK Auto Cor the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

*zoomautowerks@gmail.com

24 July 2024

Not Authored
Mr
Mony
23/7/24
d/s = 4000
4 days

REG NO.: SME 5335 X
MAKE/MODEL: HYUNDAI ELANTRA

Acknowledged by Repairer

Signature:

Date:

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY DESCRIPTION AMT(\$)

LIST ITEMS

1	Rear boot lid	2032.00	\$ 20/serf	2,049.80	—
2	Rear boot hinges		\$ 11	275.60	X
2	Rear boot lamps	295.10	\$ d/s cno	725.00	12 C
1	Rear boot lock		\$ su	250.80	X
1	Rear boot logo	4A 00	\$ neu	97.80	—
1	Rear boot "ELANTRA" emblem	48.60	\$ neu	90.90	—
2	Rear taillamps		\$ 11	801.00	X
1	Rear end panel		\$ 11	557.50	X
1	Rear end panel inner garnish		\$ 11	299.30	X
1	Rear smart keyless sensor		\$ 11	217.80	X
1	Rear bumper	481.40	\$ cre	688.74	—
2	Rear bumper top brackets		\$ 11	131.60	X
2	Rear bumper reflectors		\$ 11	199.60	X
1	Rear bumper reinforcement	294.60	\$ su	455.80	—
2	Rear bumper reinforcement stay		\$ 11	401.60	X
3	Rear bumper reinforcement brackets		\$ 11	434.70	X
2	Rear bumper side retainers		\$ 11	181.94	X
1	Rear bumper undercover		\$ 11	155.80	X
1	Rear floor board		\$ 11	259.10	X
		202	\$	8,274.38	
		Less 10%	\$	827.44	
			\$	7,446.94	

SPECIAL NETT ITEMS

1	Rear boot spoiler	\$ cre	850.00	500 S/W
1	Rear bumper clip (1 set)	\$ neu	50.00	30 S/W
1	Rear bumper lower spoiler	\$ cre	750.00	400 S/W
1	Rear number plate with holder	\$ 11	50.00	X
1	Rear reverse sensor (1 set)	\$ su	350.00	X
1	Rear reverse camera	\$ 11	480.00	X
		\$	2,530.00	

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	20
2	To remove and refit inner garnishes.	\$ 11	180.00	X
3	To remove and refit rear reverse sensor and camera.	\$	150.00	30
4	To transfer boot lid mechanism and wiring assembly.	\$	80.00	50
5	To apply undercoating.	\$	150.00	30
6	Panel beating.	\$	1,600.00	500
7	To re-spray painting on the affected areas.	\$	1,500.00	800
		\$	3,740.00	

GRAND TOTAL :

\$ 13,716.94

p- 3200.1
202
2560.08
930
1570
5000.08
11/11/24