

REF: CS/FCI24070353/Anh3 (SNJ 6443Y)

## ASSIGNMENT

Front: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estin: \_\_\_\_\_  
 OD / TP RES / OD RES / EVA / INV / MV  
 To In Vehicle No: \_\_\_\_\_  
 at W in m/s  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy: IVA  
 Claim: S No  
 Sum INS Use: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Yeh: \_\_\_\_\_

Veh No: SNJ6443Y Yr Regn: 2018, March.  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Peugeot 5008 C.D. 1199  
 Colour: Grey. A/C: Insured / Std / NI / NA  
 Sp. Reading: 128559. T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: VF3MRH NYW 14L077063  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 225/60R17.  
 R: 225/60R12

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 23/07/24.

Survey held at SMDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP 1st Cop</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>MV: 70K</u>
	<u>PV: 33.8K</u>
	<u>Nett: 36.2K</u>
	<u>Adrian confirmed lump sum \$21000 and 12 days (red, \$25059, 54%)</u>
	<u>061D</u>

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

Days Of Repair: 12

Resurvey No. of Trip: \_\_\_\_\_

1)

Date/Time, File Return to?

2)

Addl Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Inve (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

8 + RS. \$1

Photos

Others

Report Form: \_\_\_\_\_

Report Form: \_\_\_\_\_



# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SMADMIN@SM-AUTOMOTIVE.SG

Blk 1 Kaki Bukit Ave 6

Tel: (65) 6747 9241

Fax: (65) 6741 7276

20/07/2024

# 01-43

RCB No: 53231488C

GST Reg No : 53231488C

Singapore 417883

Accident date : 19/07/2024

Estimated repair cost for vehicle no : SNJ6443Y PEOGEOT 5008 ACTIVE PURETECH 1.2 EAT6  
CHASSIS: VF3MRHNYWHL077063 (2017)

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>Distorted</i>	\$1,720.00	✓ \$1,720.00
2	1	REAR BUMPER REINFORCEMENT <i>new</i>	\$860.00	+ \$860.00
3	1	RH REAR BUMPER SIDE RETAINER <i>Dist</i>	\$260.00	✓ \$260.00
4	1	RH REAR BUMPER BRACKET <i>new</i>	\$180.00	✓ \$180.00
5	1	RH REAR BUMPER REFLECTOR <i>new</i>	\$220.00	✓ \$220.00
6	1	RH REAR BUMPER CORNER PANEL <i>Distorted</i>	\$730.00	✓ \$730.00
7	1	RH REAR FENDER <i>Distorted</i>	\$2,620.00	✓ \$2,620.00
8	1	RH REAR FENDER AIR VENT <i>new</i>	\$180.00	✓ \$180.00
9	1	RH REAR FENDER OUTER GARNISH <i>Missing</i>	\$460.00	✓ \$460.00
10	1	RH REAR FENDER INNER COWLING <i>Distorted</i>	\$420.00	✓ \$420.00
11	1	RH REAR FENDER INNER TRIM BOARD <i>new</i>	\$520.00	+ \$520.00
12	1	RH REAR TAILLAMP <i>new</i>	\$860.00	✓ \$860.00
13	1	RH REAR TAILLAMP LOWER BRACKET <i>new</i>	\$160.00	+ \$160.00
14	1	REAR END PANEL <i>new</i>	\$1,360.00	✓ \$1,360.00
15	1	RH REAR FUEL COVER <i>new</i>	\$320.00	+ \$320.00
16	1	RH REAR FUEL COVER INNER GARNISH <i>new</i>	\$420.00	✓ \$420.00
17	1	RH REAR DOOR <i>Distorted</i>	\$2,650.00	✓ \$2,650.00
18	1	RH REAR DOOR LOWER GARNISH <i>Distorted</i>	\$580.00	✓ \$580.00
19	1	RH REAR DOOR WEATHER STRIPE <i>new</i>	\$260.00	✓ \$260.00
20	2	RH REAR DOOR HINGE <i>new</i>	\$210.00	+ \$420.00
21	1	RH REAR DOOR CHECKER <i>new</i>	\$190.00	+ \$190.00
22	1	RH REAR DOOR OUTER HANDLER <i>new</i>	\$360.00	+ \$360.00
23	1	RH REAR DOOR GLASS <i>new</i>	\$780.00	+ \$780.00
24	1	RH REAR DOOR POWER WINDOW GEAR & MOTOR <i>new</i>	\$820.00	✓ \$820.00
25	1	RH REAR DOOR GLASS INNER CHANNEL <i>new</i>	\$480.00	+ \$480.00
26	1	RH REAR DOOR LOCK <i>new</i>	\$590.00	+ \$590.00 ✓
27	1	RH REAR DOOR INNER TRIM BOARD <i>new</i>	\$890.00	✓ \$890.00
28	1	RH REAR DOOR GLASS OUTER CHANNEL <i>new</i>	\$430.00	+ \$430.00
29	1	RH REAR DOOR BLACK GARNISH <i>new</i>	\$360.00	✓ \$360.00
30	1	RH FRONT DOOR <i>Distorted</i>	\$2,650.00	✓ \$2,650.00



**SNJ6443Y PEOGEOT 5008**

31	1	RH FRONT DOOR LOWER GARNISH	cut	\$580.00	✓	\$580.00
32	1	RH FRONT DOOR WEATHER STRIPE	<del>new</del> New	\$260.00	✓	\$260.00
33	2	RH FRONT DOOR HINGE	3/4	\$210.00	+	\$420.00
34	1	RH FRONT DOOR CHECKER	1/2	\$190.00	+	\$190.00
35	1	RH FRONT DOOR OUTER HANDLER	Py5	\$360.00	+	\$360.00 ✓
36	1	RH FRONT DOOR GLASS	new cut	\$780.00	+	\$780.00
37	1	RH FRONT DOOR POWER WINDOW GEAR & MOTOR	new	\$820.00	+	\$820.00
38	1	RH FRONT DOOR GLASS INNER CHANNEL	new	\$480.00	+	\$480.00
39	1	RH FRONT DOOR LOCK	new	\$590.00	+	\$590.00
40	1	RH FRONT DOOR INNER TRIM BOARD	new	\$890.00	+	\$890.00
41	1	RH FRONT DOOR GLASS OUTER CHANNEL	new	\$430.00	+	\$430.00
42	1	RH FRONT DOOR BLACK GARNISH	cut	\$360.00	✓	\$360.00
43	1	RH FRONT FENDER	Devel	\$630.00	✓	\$630.00
44	1	RH FRONT FENDER OUTER GARNISH	cut	\$260.00	✓	\$260.00
45	1	RH FRONT MIRROR	Devel	\$890.00	✓	\$890.00
46	1	RH FRONT MIRROR COVER	Missing	\$160.00	✓	\$160.00
47	1	REAR AXLE BEAM	?	\$3,550.00	?	\$3,550.00
48	1	RH REAR SHOCK ABSORBER	?	\$480.00	?	\$480.00
49	1	RH REAR WHEEL BEARING	?	\$480.00	?	\$480.00
50	1	RH REAR SPORT RIM	cut	\$950.00	60/50	\$950.00
51	1	RH FRONT LOWER ARM	2	\$460.00	+	\$460.00
52	1	RH FRONT KNUCKLER ARM	2	\$790.00	+	\$790.00
53	1	RH FRONT KNUCKLER ARM BEARING	2	\$480.00	+	\$480.00
54	1	RH FRONT SHOCK ABSORBER	?	\$620.00	+	\$620.00
55	1	RH FRONT SPORT RIM	new	\$950.00	X	\$950.00

Supplementary

① RH rear door lock inner mechanism - \$365.00

<b>TOTAL :</b>	<b>\$39,610.00</b>
<b>LESS 10 %</b>	<b>\$3,961.00</b>
<b>SUB-TOTAL :</b>	<b>\$35,649.00</b>

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS	\$80.00	\$80.00
2	1	RH REAR FENDER QUARTER GLASS SEALANT	\$120.00	\$120.00
3	1	RH REAR FENDER OUTER GARNISH CLIPS	\$60.00	\$60.00
4	1	REAR END PANEL SEALANT	\$120.00	\$120.00
5	1	RH REAR FENDER SEALANT	\$120.00	\$120.00
6	1	RH REAR FENDER INNER COWLING CLIPS	\$50.00	\$50.00
7	1	RH REAR DOOR LOWER GARNISH CLIPS	\$50.00	\$50.00
8	1	RH FRONT DOOR LOWER GARNISH CLIPS	\$50.00	\$50.00



**SNJ6443Y PEOGEOT 5008**

9	1	RH FRONT FENDER GARNISH CLIPS <i>me</i>	\$50.00	<i>20</i>	<del>\$50.00</del>
10	1	RH REAR TYRE <i>JH</i>	\$620.00	<i>8</i>	<del>\$620.00</del>
11	1	RH FRONT TYRE <i>JH</i>	\$620.00	<i>8</i>	<del>\$620.00</del>

**TOTAL:** \$1,940.00

**TOTAL PARTS:** \$37,589.00

**Labour charges**

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 LABOUR FOR REMOVE & REFIX RH REAR UPHOLSTERY, CUSHION SEAT, CARPET
- 5 LABOUR FOR REMOVE & REFIX REAR FENDER QUARTER GLASS
- 6 LABOUR FOR REMOVE & RENEW REAR UNDER CARRIAGE
- 7 LABOUR FOR REMOVE & RENEW RH FRONT UNDER CARRIAGE
- 8 LABOUR FOR REMOVE & TRANSFER ALL RH BOTH DOOR FITTING
- 9 TO CONDUCT WHEEL ALIGNMENT
- 10 TO CHECK & RESET WARNING LIGHT ON

*1200*  
\$2,800.00  
*1000* ~~\$2,600.00~~  
*30* ~~\$120.00~~  
*60* ~~\$600.00~~  
*60* ~~\$150.00~~  
*7* ~~\$500.00~~  
*X* ~~\$400.00~~  
*160* ~~\$800.00~~  
*80* ~~\$200.00~~  
*180* ~~\$300.00~~

**Subtotal :-** \$8,470.00

**Total:-** \$46,059.00

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: