

REF:

ASSIGNMENT

Front: _____ Date: _____
 Estin: ^{Est Post} _____
 OD / ~~TP~~ / TP RES / OD RES / EVA / INV / MV
 To In ~~Vehicle~~ No: _____
 at W ~~Est Post~~ / m/s _____
 of _____
 Insured: _____
 Policy: ~~PA~~ _____
 Claim: ~~S No~~ _____
 Sum ~~INS~~ / ~~Est~~ / ~~Post~~ / ~~Excess~~: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SNJ6443Y Yr Regn: 2018, March.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Peugeot 5008 C.D. 1199
 Colour: Grey. A/C: Insured / Std / NI / NA
 Sp. Reading: 128559. T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: VF3MRH NYW 14L077063
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/60R17.
 R: 225/60R12

(Policy Condition)

Remark: Veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 23/07/24.

Survey held at SM
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP 1st Cap</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>MV: 70K</u>
	<u>PV: 33.8K</u>
	<u>Nett: 36.2K</u>
	<u>061D</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

1)

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Addl Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Inve (\$ _____)

Survey Fee: _____

Transportation: _____

8 + RS. \$1

Photos

Others

Report Form:

Report Form:

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SMADMIN@SM-AUTOMOTIVE.SG

Blk 1 Kaki Bukit Ave 6

Tel: (65) 6747 9241

Fax: (65) 6741 7276

01-43

RCB No: 53231488C

GST Reg No : 53231488C

20/07/2024

Singapore 417883

Accident date : 19/07/2024

Estimated repair cost for vehicle no : SNJ6443Y PEOGEOT 5008 ACTIVE PURETECH 1.2 EAT6
CHASSIS: VF3MRHNYWHL077063 (2017)

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>Distorted</i>	\$1,720.00	✓ \$1,720.00
2	1	REAR BUMPER REINFORCEMENT <i>new</i>	\$860.00	+ \$860.00
3	1	RH REAR BUMPER SIDE RETAINER <i>Dist</i>	\$260.00	✓ \$260.00
4	1	RH REAR BUMPER BRACKET <i>new</i>	\$180.00	✓ \$180.00
5	1	RH REAR BUMPER REFLECTOR <i>new</i>	\$220.00	✓ \$220.00
6	1	RH REAR BUMPER CORNER PANEL <i>Distorted</i>	\$730.00	✓ \$730.00
7	1	RH REAR FENDER <i>Distorted</i>	\$2,620.00	✓ \$2,620.00
8	1	RH REAR FENDER AIR VENT <i>new</i>	\$180.00	✓ \$180.00
9	1	RH REAR FENDER OUTER GARNISH <i>Missing</i>	\$460.00	✓ \$460.00
10	1	RH REAR FENDER INNER COWLING <i>Distorted</i>	\$420.00	✓ \$420.00
11	1	RH REAR FENDER INNER TRIM BOARD <i>new</i>	\$520.00	+ \$520.00
12	1	RH REAR TAILLAMP <i>new</i>	\$860.00	✓ \$860.00
13	1	RH REAR TAILLAMP LOWER BRACKET <i>new</i>	\$160.00	+ \$160.00
14	1	REAR END PANEL <i>new</i>	\$1,360.00	✓ \$1,360.00
15	1	RH REAR FUEL COVER <i>new</i>	\$320.00	+ \$320.00
16	1	RH REAR FUEL COVER INNER GARNISH <i>new</i>	\$420.00	✓ \$420.00
17	1	RH REAR DOOR <i>Distorted</i>	\$2,650.00	✓ \$2,650.00
18	1	RH REAR DOOR LOWER GARNISH <i>Distorted</i>	\$580.00	✓ \$580.00
19	1	RH REAR DOOR WEATHER STRIPE <i>new</i>	\$260.00	✓ \$260.00
20	2	RH REAR DOOR HINGE <i>new</i>	\$210.00	+ \$420.00
21	1	RH REAR DOOR CHECKER <i>new</i>	\$190.00	+ \$190.00
22	1	RH REAR DOOR OUTER HANDLER <i>new</i>	\$360.00	+ \$360.00
23	1	RH REAR DOOR GLASS <i>new</i>	\$780.00	+ \$780.00
24	1	RH REAR DOOR POWER WINDOW GEAR & MOTOR <i>new</i>	\$820.00	✓ \$820.00
25	1	RH REAR DOOR GLASS INNER CHANNEL <i>new</i>	\$480.00	+ \$480.00
26	1	RH REAR DOOR LOCK <i>new</i>	\$590.00	+ \$590.00 ✓
27	1	RH REAR DOOR INNER TRIM BOARD <i>new</i>	\$890.00	✓ \$890.00
28	1	RH REAR DOOR GLASS OUTER CHANNEL <i>new</i>	\$430.00	+ \$430.00
29	1	RH REAR DOOR BLACK GARNISH <i>new</i>	\$360.00	✓ \$360.00
30	1	RH FRONT DOOR <i>Distorted</i>	\$2,650.00	✓ \$2,650.00

SNJ6443Y PEOGEOT 5008

31	1	RH FRONT DOOR LOWER GARNISH	cut	\$580.00	✓	\$580.00
32	1	RH FRONT DOOR WEATHER STRIPE	new New	\$260.00	✓	\$260.00
33	2	RH FRONT DOOR HINGE	3/4	\$210.00	+	\$420.00
34	1	RH FRONT DOOR CHECKER	1/2	\$190.00	+	\$190.00
35	1	RH FRONT DOOR OUTER HANDLER	Py5	\$360.00	+	\$360.00 ✓
36	1	RH FRONT DOOR GLASS	new cut	\$780.00	+	\$780.00
37	1	RH FRONT DOOR POWER WINDOW GEAR & MOTOR	new	\$820.00	+	\$820.00
38	1	RH FRONT DOOR GLASS INNER CHANNEL	new	\$480.00	+	\$480.00
39	1	RH FRONT DOOR LOCK	new	\$590.00	+	\$590.00
40	1	RH FRONT DOOR INNER TRIM BOARD	new	\$890.00	+	\$890.00
41	1	RH FRONT DOOR GLASS OUTER CHANNEL	new	\$430.00	+	\$430.00
42	1	RH FRONT DOOR BLACK GARNISH	cut	\$360.00	✓	\$360.00
43	1	RH FRONT FENDER	Devel	\$630.00	✓	\$630.00
44	1	RH FRONT FENDER OUTER GARNISH	cut	\$260.00	✓	\$260.00
45	1	RH FRONT MIRROR	Devel	\$890.00	✓	\$890.00
46	1	RH FRONT MIRROR COVER	Missing	\$160.00	✓	\$160.00
47	1	REAR AXLE BEAM	?	\$3,550.00	?	\$3,550.00
48	1	RH REAR SHOCK ABSORBER	?	\$480.00	?	\$480.00
49	1	RH REAR WHEEL BEARING	?	\$480.00	?	\$480.00
50	1	RH REAR SPORT RIM	cut	\$950.00	60/50	\$950.00
51	1	RH FRONT LOWER ARM	2	\$460.00	+	\$460.00
52	1	RH FRONT KNUCKLER ARM	2	\$790.00	+	\$790.00
53	1	RH FRONT KNUCKLER ARM BEARING	1/2	\$480.00	+	\$480.00
54	1	RH FRONT SHOCK ABSORBER	↓	\$620.00	+	\$620.00
55	1	RH FRONT SPORT RIM	new	\$950.00	X	\$950.00

Supplementary

① RH rear door lock inner mechanism - \$365.00

TOTAL :	\$39,610.00
LESS 10 %	\$3,961.00
SUB-TOTAL :	\$35,649.00

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS	\$80.00	\$80.00
2	1	RH REAR FENDER QUARTER GLASS SEALANT	\$120.00	\$120.00
3	1	RH REAR FENDER OUTER GARNISH CLIPS	\$60.00	\$60.00
4	1	REAR END PANEL SEALANT	\$120.00	\$120.00
5	1	RH REAR FENDER SEALANT	\$120.00	\$120.00
6	1	RH REAR FENDER INNER COWLING CLIPS	\$50.00	\$50.00
7	1	RH REAR DOOR LOWER GARNISH CLIPS	\$50.00	\$50.00
8	1	RH FRONT DOOR LOWER GARNISH CLIPS	\$50.00	\$50.00

SNJ6443Y PEOGEOT 5008

9	1	RH FRONT FENDER GARNISH CLIPS <i>me</i>	\$50.00	<i>20</i>	\$50.00
10	1	RH REAR TYRE <i>JH</i>	\$620.00	<i>8</i>	\$620.00
11	1	RH FRONT TYRE <i>JH</i>	\$620.00	<i>8</i>	\$620.00

TOTAL: \$1,940.00

TOTAL PARTS: \$37,589.00

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 LABOUR FOR REMOVE & REFIX RH REAR UPHOLSTERY, CUSHION SEAT, CARPET
- 5 LABOUR FOR REMOVE & REFIX REAR FENDER QUARTER GLASS
- 6 LABOUR FOR REMOVE & RENEW REAR UNDER CARRIAGE
- 7 LABOUR FOR REMOVE & RENEW RH FRONT UNDER CARRIAGE
- 8 LABOUR FOR REMOVE & TRANSFER ALL RH BOTH DOOR FITTING
- 9 TO CONDUCT WHEEL ALIGNMENT
- 10 TO CHECK & RESET WARNING LIGHT ON

1200
\$2,800.00
1000 ~~\$2,600.00~~
30 ~~\$120.00~~
60 ~~\$600.00~~
60 ~~\$150.00~~
7 ~~\$500.00~~
X ~~\$400.00~~
160 ~~\$800.00~~
80 ~~\$200.00~~
180 ~~\$300.00~~

Subtotal :- \$8,470.00

Total:- \$46,059.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: