

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP RES / CD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNC3230B Regn: 2021 / oct

Type: MC Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Able C.D. 1198

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 147372 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNIFAAE1320900450

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / I / IZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or Roadstone

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 23/07/24

Survey held at Techwerkz

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction

TP 1st Cap.

COE Expiry: _____

Estimate given during: Yes C

1st Survey: No C

MV: 105K

PV: 85.8K

Nett: 69.2K

659M

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$

Photos

Others

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)

Report Formed:

Report Formed:

TECHWERKZ AUTOMOTIVE PTE. LTD.

BLK 8 KAKI BUKIT AVE 4 #05-15 PREMIER@ KAKI BUKIT
Singapore 415874

Estimate for SNC3230B(Nissan Note)

*HEADLAMP RH	<i>3 new</i>	\$1,200.00	X
*FRONT BUMPER		\$685.00	+
*FRONT BUMPER SIDE RETAINER LH & RH	<i>new</i>	\$120.00	+
*FRONT BUMPER CLIPS	<i>new</i>	\$50.00	+
*FRONT FENDER RH	<i>Detached</i>	\$660.00	—
*FRONT FENDER COWLING RH	<i>3 new</i>	\$140.00	+
*FRONT FENDER COWLING CLIPS		\$50.00	+
*FRONT FENDER BKT FRT RH	<i>new</i>	\$60.00	X
*WASHER TANK	<i>new</i>	\$190.00	+
*FRONT DOOR RH	<i>Detached</i>	\$920.00	✓
*FRONT DOOR HINGE UPPER & LOWER		\$240.00	+
*FRONT DOOR CHECKER	<i>3 new</i>	\$155.00	+
*FRONT DOOR POWER WINDOW MOTOR		\$360.00	+
*FRONT DOOR POWER WINDOW REGULATOR	<i>new</i>	\$390.00	+
*FRONT DOOR INNER TRIMBOARD	<i>3 new</i>	\$455.00	+
*FRONT DOOR INNER LOCK		\$680.00	+
*FRONT DOOR WEATHERSTRIP (AT DOOR)	<i>3 new</i>	\$80.00	+
*FRONT DOOR WEATHERSTRIP (AT BODY)		\$215.00	+
*FRONT DOOR TAPE FRT & RR	<i>new</i>	\$80.00	✓
*FRONT DOOR OUTER HANDLE	<i>3 not new</i>	\$195.00	X
*FRONT DOOR OUTER HANDLE COVER		\$160.00	+
*SIDE MIRROR RH		\$630.00	+
*SIDE MIRROR COVER RH		\$190.00	+
*SIDE MIRROR LOWER COVER RH	<i>3 new</i>	\$150.00	+
*FRONT DOOR PILLAR RH	<i>new</i>	\$980.00	+
*FRONT DOOR QTR GLASS MLDG RH	<i>new</i>	\$285.00	+
*FRONT WHEEL BEARING RH	<i>new</i>	\$270.00	✓
*FRONT WHEEL HUB RH		\$480.00	+
*FRONT KNUCKLE ARM RH	<i>3 new</i>	\$820.00	+
*FRONT LOWER ARM RH		\$530.00	+
*FRONT SHOCK ABSORBER RH		\$430.00	+
*FRONT SHOCK ABSORBER TOP MOUNTING RH		\$120.00	X
*FRONT SHOCK ABSORBER TOP MOUNTIGN BEARING RH	<i>3 new</i>	\$60.00	+
*FRONT STABILISER BAR		\$550.00	+
*FRONT DRIVE SHAFT RH		\$830.00	+
*FRONT STEERING RACK	<i>Not</i>	\$2,450.00	+
*FRONT CROSSMEMBER	<i>new</i>	\$800.00	+
*FRONT RH RIM		\$1,320.00	+
		\$17,980.00	
		\$1,798.00	
		\$16,182.00	

Less 10%

Front RH Tyre

Not in

~~\$550.00~~

~~\$550.00~~

x

TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.

~~\$40.00~~ *30*

TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.

~~\$150.00~~ *80*

TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.

~~\$180.00~~ *60*

TO DISMANTLE; REPLACE AND REINSTALL UNDERCARRIAGE. FRT

~~\$400.00~~ *60*

LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT

~~\$250.00~~ *x*

TO DISMANTLE ALL DAMAGED PARTS.

~~\$1,500.00~~ *400*

TO SPRAY PAINT DAMAGED PORTION

~~\$1,500.00~~ *600*

\$4,020.00

Total

\$20,752.00

Adrian L

h/s 23/07/24

05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: