

# TECHWERKZ AUTOMOTIVE PTE. LTD.

BLK 8 KAKI BUKIT AVE 4 #05-15 PREMIER@ KAKI BUKIT  
Singapore 415874

TP 1st Cap

Veron.

Estimate for SNC3230B(Nissan Note)

|                                               |           |             |   |
|-----------------------------------------------|-----------|-------------|---|
| *HEADLAMP RH                                  | { new     | \$1,200.00  | X |
| *FRONT BUMPER                                 |           | \$685.00    | + |
| *FRONT BUMPER SIDE RETAINER LH & RH           | new       | \$120.00    | + |
| *FRONT BUMPER CLIPS                           | new       | \$50.00     | + |
| *FRONT FENDER RH                              | Deaded    | \$660.00    | — |
| *FRONT FENDER COWLING RH                      | { new     | \$140.00    | + |
| *FRONT FENDER COWLING CLIPS                   |           | \$50.00     | + |
| *FRONT FENDER BKT FRT RH                      | new       | \$60.00     | X |
| *WASHER TANK                                  | new       | \$190.00    | + |
| *FRONT DOOR RH                                | Deaded    | \$920.00    | ✓ |
| *FRONT DOOR HINGE UPPER & LOWER               | { new     | \$240.00    | + |
| *FRONT DOOR CHECKER                           |           | \$155.00    | + |
| *FRONT DOOR POWER WINDOW MOTOR                |           | \$360.00    | + |
| *FRONT DOOR POWER WINDOW REGULATOR            | new       | \$390.00    | + |
| *FRONT DOOR INNER TRIMBOARD                   | { new     | \$455.00    | + |
| *FRONT DOOR INNER LOCK                        |           | \$680.00    | + |
| *FRONT DOOR WEATHERSTRIP (AT DOOR)            | { new     | \$80.00     | + |
| *FRONT DOOR WEATHERSTRIP (AT BODY)            |           | \$215.00    | + |
| *FRONT DOOR TAPE FRT & RR                     | new       | \$80.00     | ✓ |
| *FRONT DOOR OUTER HANDLE                      | { not new | \$195.00    | X |
| *FRONT DOOR OUTER HANDLE COVER                |           | \$160.00    | + |
| *SIDE MIRROR RH                               |           | \$630.00    | + |
| *SIDE MIRROR COVER RH                         | {         | \$190.00    | + |
| *SIDE MIRROR LOWER COVER RH                   | { new     | \$150.00    | + |
| *FRONT DOOR PILLAR RH                         |           | \$980.00    | + |
| *FRONT DOOR QTR GLASS MLDG RH                 | new       | \$285.00    | + |
| *FRONT WHEEL BEARING RH                       | new       | \$270.00    | ✓ |
| *FRONT WHEEL HUB RH                           | {         | \$480.00    | + |
| *FRONT KNUCKLE ARM RH                         | { new     | \$820.00    | + |
| *FRONT LOWER ARM RH                           |           | \$530.00    | + |
| *FRONT SHOCK ABSORBER RH                      |           | \$430.00    | + |
| *FRONT SHOCK ABSORBER TOP MOUNTING RH         | { new     | \$120.00    | X |
| *FRONT SHOCK ABSORBER TOP MOUNTIGN BEARING RH |           | \$60.00     | + |
| *FRONT STABILISER BAR                         | {         | \$550.00    | + |
| *FRONT DRIVE SHAFT RH                         |           | \$830.00    | X |
| *FRONT STEERING RACK                          | { Not     | \$2,450.00  | + |
| *FRONT CROSSMEMBER                            |           | \$800.00    | + |
| *FRONT RH RIM                                 | { new     | \$1,320.00  | + |
|                                               |           | \$17,980.00 |   |
|                                               |           | \$1,798.00  |   |
|                                               |           | \$16,182.00 |   |

Less 10%

1930

less 10%: 1737

Front RH Tyre

*Not NW*

\$550.00

\$550.00

*X*

TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.

~~\$40.00~~

*30*

TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.

~~\$150.00~~

*80*

TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.

~~\$180.00~~

*60*

TO DISMANTLE; REPLACE AND REINSTALL UNDERCARRIAGE. FRT

~~\$400.00~~

*60*

LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT

~~\$250.00~~

*X*

TO DISMANTLE ALL DAMAGED PARTS.

~~\$1,500.00~~

*400*

TO SPRAY PAINT DAMAGED PORTION

~~\$1,500.00~~

*600*

\$4,020.00

Total

\$20,752.00

*Adrian Ly*

*h/s 23/07/24*

*05 Days.*

*total: 2967*

*h/s: 2350*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: