



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE SINGAPORE 757705

INV No. : SAC2400195

INV Date : 02-08-2024

Reference CS3/SMR24070355/Kqh3m4

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. SJY 6785D

Insured Veh. SG 5574R

Claim No. BUS/07/24/5040

Policy No.

Accident Date 22/07/2024

Inspection Date 24/07/2024

Description	Amount
Pre-Repair Survey	128.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS STRIDES PREMIER AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		Ref:	CS3/SMR24070355/Kqh3m4	
		Date:	02/08/2024	
		Code:	SMR	
1. Policy Particulars :- PRE-REPAIR SURVEY				
Insured Veh.	SG 5574R	Veh. Inspected	SJY 6785D	
Policy No.	-	Coverage	0	
Claim No.	BUS/07/24/5040	Excess	\$0.00	
Assign From	HUA YEN	Assign Date	23/07/2024	
2. Vehicle Details				
Make & Model	TOYOTA VIOS E AUTO	C.C	1497	
Engine No.	1NZY106347	Year of Reg.	23/09/2010	
Chassis No.	MR053HY9305169739	Colour	METALLIC LIGHT GREEN	
Odometer	123551 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	185/60R15	KAPSEN	8	
L/H Front Tyre	185/60R15	KAPSEN	8	
R/H Rear Tyre	185/60R15	ACHILLES	6	
L/H Rear Tyre	185/60R15	ACHILLES	6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
5. General Information				
Accident Date	22/07/2024	Inspection Date	24/07/2024 (10:52)	
Survey held at	KUM CHEW MOTOR WORKSHOP - 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 1 of 7)

PHOTOGRAPHS FOR VEHICLE NO. : SJY 6785D





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 2 of 7)

PHOTOGRAPHS FOR VEHICLE NO. : SJY 6785D



PHOTOGRAPHS FOR VEHICLE NO. : SJY 6785D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 7)

PHOTOGRAPHS FOR VEHICLE NO. : SJY 6785D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.

19-9607198-R

INSPECTION PHOTOS (Page 5 of 7)

PHOTOGRAPHS FOR VEHICLE NO. : SJY 6785D



PHOTOGRAPHS FOR VEHICLE NO. : SJY 6785D



PHOTOGRAPHS FOR VEHICLE NO. : SJY 6785D



PHOTOGRAPHS FOR VEHICLE NO. : SJY 6785D



PHOTOGRAPHS FOR VEHICLE NO. : SJY 6785D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 3 of 3)

PHOTOGRAPHS FOR VEHICLE NO. : SJY 6785D



PHOTOGRAPHS FOR VEHICLE NO. : SJY 6785D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SJY 6785D

