BLUWEL AUTOMOTIVE SERVICE PTE LTD 1 KAKI BUKIT AVE 6 # 01-28/53/55/56 SINGAPORE 417883 TEL :67452088

VEHICLE No: SKW 7216Y

1PC FRONT BUMPER DIS/TOIN 1PC FRONT BUMPER BEAM A 1 1PC FRONT BUMPER LAMP N/S C/A 1PC FRONT BUMPER FOG LAMP N/S O/A 1PC FRONT BUMPER FOG LAMP GARNISH N/S TOIN 1PC FRONT BUMPER SIDE RETAINER N/S C/A 1SET FRONT BUMPER CLIPS AM \$550.00 1PC FRONT BUMPER LOWER LIP C/A / ALC 1PC FRONT FENDER N/S DISAFT \$334.00 1PC FRONT FENDER INNER SHIELD CLIPS N/S AM \$30.00 1PC FRONT GRILLE ASSY AN \$5527.50 1PC HEADLAMP N/S C/A 1PC FRONT SUPPORT PANEL AN \$5588.30 1PC FRONT SUPPORT PANEL AN \$588.30 1PC FRONT LOWER ARM N/S AN \$366.20 1PC FRONT KNUCKLE ARM BEARING N/S AN \$188.50 \$995.01 \$5995.01 \$5995.01 \$517.20 \$517.20 \$517.20 \$517.20 \$526.50 \$378.00 \$142.60 \$50.00
25/6 77,526.24

TO CHECK WIRING
TO RESET & DIAGNOSTIC SYSTEM
TO SPRAY RUST PROOFING
TO CONDUCT WHEEL ALIGNMENT
TO DISMANTLE FRONT UNDER CARRIAGE
TO REFILL AIR CON GAS
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$50.00 20 \$180.00 \times \$50.00 30 \$100.00 60 \$180.00 \times \$120.00 \times \$680.00 \times \$880.00 600 TOTAL \$10,168.24

Not Authorial Merus 13/6/24

LKK Auto Consultants hence notify
the Repairer of the following:
To recurvey before/after spray points.
To display damaged part,
Parts prices are subject to confirmation
No illagal modification(s) is allowed
Supplementary item(s) must be recurred to is subject to final approval from Insurance day year.

Acknowledged by Repairer
Signature:
Date: