BLUWEL AUTOMOTIVE SERVICE PTE LTD 1 KAKI BUKIT AVE 6 # 01-28/53/55/56 SINGAPORE 417883 TEL:67452088

VEHICLE No: SKW 7216Y

			\$995.00
1PC	FRONT BUMPER		\$517.20
1PC	FRONT BUMPER BEAM		\$266.50
1PC	FRONT BUMPER LAMP N/S		\$378.00
1PC	FRONT BUMPER FOG LAMP N/S		\$142.60
1PC	FRONT BUMPER FOG LAMP GARNISH N/S		\$56.20
1PC	FRONT BUMPER SIDE RETAINER N/S	10	\$50.00
1SET	FRONT BUMPER CLIPS		\$650.00
1PC	FRONT BUMPER LOWER LIP		\$334.00
1PC	FRONT FENDER N/S		
1PC	FRONT FENDER INNER SHIELD N/S		\$112.30
1SET	FRONT FEBDER INNER SHIELD CLIPS N/S		\$30.00
1PC	FRONT GRILLE ASSY		\$527.50
1PC	HEADLAMP N/S		\$2,976.00
1PC	HEADLAMP PANEL N/S		\$250.50
1PC	FRONT SUPPORT PANEL		\$588.30
1PC	FRONT SPORT RIM N/S		\$1,100.00
1PC	FRONT LOWER ARM N/S		\$366.20
1PC	FRONT KNUCKLE ARM N/S		\$381.50
1PC	FRONT KNUCKLE ARM BEARING N/S		\$188.50
7. 7			\$9,910.30
		LESS 20%	\$7,928.24
	TO CHECK WIRING		\$50.00
	TO RESET & DIAGNOSTIC SYSTEM		\$180.00
	TO SPRAY RUST PROOFING		\$50.00
	TO CONDUCT WHEEL ALIGNMENT		\$100.00
			\$180.00
	TO DISMANTLE FRONT UNDER CARRIAGE		\$120.00
	TO REFILL AIR CON GAS		\$680.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS		\$880.00
	TO PUTTY & SPRAY PAINTING		3000.00

LKK Auto Consultants hence notify the Repairer of the following:

TOTAL

\$10,168.24

- To resurvey before/after spray point;
- To display damaged parks,
- = Parts prices are subject to confir it heat
- a Third party survey is on a "Without Property of a Chall.
- No Elegal modification(s) is ellowed
- Supplementary Item(a) must be required is subject to final approval from insurance to

Acknowledged by Repairer

Signatur

Date