

JC Motor Consultancy

UEN No: 53383584D // Email: jcmotorconsultancy@gmail.com

Vehicle number: SKQ697U

Vehicle Made & Model: TOYOTA ESTIMA

<u>Qty</u>	<u>List Items</u>	<u>Amount \$</u>
1	Front door - LH <i>20/3ent</i>	2,126.30 ✓
1	Front door outer garnish <i>20/70.1</i>	978.10 ✓
1	Front door outer garnish moulding <i>111</i>	281.60 ✓
1	Front door glass outer moulding <i>11</i>	261.90 X
1	Front door glass run channel <i>11</i>	288.63 X
1	Front door w/strip <i>11</i>	241.66 X
1	Front door insulation <i>11</i>	130.20 X
1	Front door checker <i>11</i>	115.60 X
1	Front fender - LH <i>11</i>	977.20 X
1	Front fender protector <i>20/70.1</i>	311.43 ✓
1	Front fender inner shield <i>11</i>	254.63 X
1	Front shock absorber - LH <i>11</i>	581.60 X
1	Front shock absorber top mount <i>11</i>	210.50 X
1	Front lower arm <i>but</i>	769.50 ✓
1	Front lower arm ball joint <i>11</i>	211.60 X
1	Front knuckle arm <i>11</i>	610.70 X
1	Front wheel hub bearing <i>Daye</i>	761.90 ✓
	<i>520</i>	
	Sub-total	9,113.05
	Less 25%	2,278.26
	Total List	6,834.79

*no + Authorised
her
24/7/24
1/58 4400/
tub ph. 111111
3 days*

Vehicle number: SKQ697U

Vehicle Made & Model: TOYOTA ESTIMA

Special Nett Items

1 set	Front door outer garnish clip	11	120.00	X
1 set	Front fender inner shield clip	11	80.00	X
1	Front sport wheel - LH	wopid	650.00	600 s/w
1	Front tyre - LH	11	350.00	X
1 set	Front door visor	her	350.00	60 s/w
Total Special Nett			<u>1,550.00</u>	

Labour charges

To remove, front undercarriage	250.00	120
To check wheel alignment	120.00	60
To respray undercoating	100.00	30
To respray painting and etc.	1,080.00	600
Panel beating, cut, weld, remove & replacing above parts	800.00	300
Total Labour	<u>2,350.00</u>	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 10,734.79

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-498693
252
3740.19
660
1100
5512.19
202
4408