



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Ms Kwek Ying Xiu 58 Trevoze Crescent #02-13 Singapore 298089 Contact No Mobile: 98715693	Cust No/Name	/Ms Kwek Ying Xiu
	Reg No/Reg Date	SMN6269A / 22/08/2019
	Date In/Mileage	/ 0
	Chassis No	KNAD6811VL6325696
	Engine No	G3LCKP079250
	Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim	BEG SIGNAL RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00087	Cash	17/07/2024/ 12:14		1210/ Lim Teng Keat	11098		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
Z TEXT							
TP CLAIM SMRT							
DOA 07/07/2024							
SUR							
00 REPAIR DAYS							
E PNT88000							3200.00
TO REPLACE REAR BUMPER, TAIL GATE, REPAIR ACCIDENT AFFECTED AREA							
E PNT98000							1650.00
PAINT WORK ON REAR BUMPER, TAIL GATE							
E PNT88000							150.00
TO REMOVE & REFIT REAR PARKING SENSOR							
E PNT88000							960.00
TO TRANSFER PARTS & COMPONENTS TO NEW TAIL GATE							
E PNT88000							380.00
TO REMOVE & REFIT REAR WINDSCREEN							
M SUNDRY							120.00
SUPPLY WINDSCREEN SEALANT							
E PNT88000							150.00
PERFORM WATER LEAK TEST							
A 54900099							150.00
TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							380.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
M SUNDRY							80.00
SUNDRIES							
M SUNDRY							50.00
C&C EMBLEM							
M SUNDRY							85.00
TO SUPPLY 1 PCS NUMBER PLATE WITH CASING							
M PANEL ASSY-TAIL GATE					1.00	1530.00 00.00	1530.00
M LOGO ASSY-KIA SUB					1.00	61.00 00.00	61.00
M EMBLEM-STONIC					1.00	26.00 00.00	26.00

Confirm & accepted by

 Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Ms Kwek Ying Xiu 58 Trevoze Crescent #02-13 Singapore 298089 Contact No Mobile: 98715693	Cust No/Name	/Ms Kwek Ying Xiu
	Reg No/Reg Date	SMN6269A / 22/08/2019
	Date In/Mileage	/ 0
	Chassis No	KNAD6811VL6325696
	Engine No	G3LCKP079250
	Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim	BEG SIGNAL RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00087	Cash	17/07/2024/ 12:14		1210/ Lim Teng Keat	11098

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M EMBLEM-TURBO G.D.I	1.00	38.00	00.00	38.00
M GARNISH-T/GATE UPR,RH	1.00	66.00	00.00	66.00
M GARNISH-T/GATE UPR,LH	1.00	66.00	00.00	66.00
M PAD-WINDSHIELD GLASS	12.00	2.00	00.00	24.00
M STOPPER-RR WINDOW GLASS	2.00	4.00	00.00	8.00
M PAD-WINDSHIELD	2.00	17.00	00.00	34.00
M GROMMET-REAR WIPER	1.00	5.00	00.00	5.00
M CLIP	8.00	5.00	00.00	40.00
M TERMINAL-RR WDO GLASS DEFOGGER	2.00	7.00	00.00	14.00
M LAMP ASSY-LICENSE PLATE	2.00	71.00	00.00	142.00
M RR CAMERA & TRUNK LID HDL ASSY	1.00	690.00	00.00	690.00
M COVER-RR BUMPER LWR	1.00	531.00	00.00	531.00
M SKID PLATE-RR BUMPER	1.00	167.00	00.00	167.00

Confirm & accepted by

Nett	10,797.00
9% GST on	10797.00
	971.73
Total Payable	11,768.73

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.