



CYCLE & CARRIAGE

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-85001111-X

Invoice Name & Address		Owner Name & Vehicle Info	
Ms Kwek Ying Xiu		Cust No/Name	/Ms Kwek Ying Xiu
58 Trevoise Crescent		Reg No/Reg Date	SMN6269A / 22/08/2019
#02-13		Date In/Mileage	/ 0
Singapore 298089		Chassis No	KNAD6811VL6325696
		Engine No	G3LCKP079250
		Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF
Contact No Mobile: 98715693		Colour/Trim	BEG SIGNAL RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM000087	Cash	29/07/2024/ 10:34		1210/ Lim Teng Keat	11098

Description of Goods / Services

Qty	Unit Price	Disc%	Amount
Z TEXT			
TP CLAIM SMRT			
DOA 07/07/2024			
SUR			
00 REPAIR DAYS			
E PNT88000			1280 3200.00
TO REPLACE REAR BUMPER, TAIL GATE,			
REPAIR ACCIDENT AFFECTED AREA			
E PNT98000			825 1650.00
PAINT WORK ON REAR BUMPER, TAIL GATE			
E PNT88000			80 150.00
TO REMOVE & REFIT REAR PARKING SENSOR			
E PNT88000			320 960.00
TO TRANSFER PARTS & COMPONENTS TO NEW TAIL GATE			
E PNT88000			280 380.00
TO REMOVE & REFIT REAR WINDSCREEN			
M SUNDRY			120.00
SUPPLY WINDSCREEN SEALANT			
E PNT88000			80 150.00
PERFORM WATER LEAK TEST			
A 54900099			120 150.00
TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM			
A 10028901			380.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM			
M SUNDRY			20 80.00
SUNDRIES			
M SUNDRY			50.00
C&C EMBLEM			
M SUNDRY			85.00
TO SUPPLY 1 PCS NUMBER PLATE WITH CASING			
M PANEL ASSY-TAIL GATE	1.00	1530.00	00.00
M LOGO ASSY-KIA SUBA	1.00	61.00	00.00
M EMBLEM-STONIC	1.00	26.00	00.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
Ms Kwek Ying Xiu		Cust No/Name	/Ms Kwek Ying Xiu
58 Trevoise Crescent #02-13 Singapore 298089		Reg No/Reg Date	SMN6269A / 22/08/2019
Contact No Mobile: 98715693		Date In/Mileage	/ 0
		Chassis No	KNAD6811VL6325696
		Engine No	G3LCKP079250
		Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF
		Co/our/Trim	BEG SIGNAL RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00087	Cash	29/07/2024/ 10:34		1210/ Lim Teng Keat	11098

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M EMBLEM-TURBO G.D.I	1.00	38.00	00.00	38.00
M GARNISH-T/GATE UP, RH	1.00	66.00	00.00	66.00
M GARNISH-T/GATE UP, LH	1.00	66.00	00.00	66.00
M PAD-WINDSHIELD GLASS	12.00	2.00	00.00	24.00
M STOPPER-RR WINDOW GLASS	2.00	4.00	00.00	8.00
M PAD-WINDSHIELD	2.00	17.00	00.00	34.00
M GROMMET-REAR WIPER	1.00	5.00	00.00	5.00
M CLIP	8.00	5.00	00.00	40.00
M TERMINAL-RR WDO GLASS DEFOGGER	2.00	7.00	00.00	14.00
M LAMP ASSY-LICENSE PLATE	2.00	71.00	00.00	142.00
M RR CAMERA & TRUNK LID HDL ASSY	1.00	690.00	00.00	690.00
M COVER-RR BUMPER LWR	1.00	531.00	00.00	531.00
M SKID PLATE-RR BUMPER	1.00	167.00	00.00	167.00

SURVEYOR NAME: Pang - HengSURVEYOR SIGNATURE: [Signature]DATE: 27/07/24REMARKS: 4 daysPang 54 part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized Signature of Repairer company stamp

Signature:

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windshield in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windshield.