



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TPSMRT.
Voron

I-DEAL AUTO TRADING PRIVATE LIMITED
18 SIN MING LANE #03-06 MIDVIEW CITY
SINGAPORE 573960

TAX INVOICE

Contact : 87789969 98191208

Repair Code : CLM18312
Date in : 14/12/2024
Vehicle Num. : GBE6288Y
Model : TOYOTA HIACE VAN TURBO 5 DR MANUAL
Chassis/Eng# : JTFHT02P400189974/1KD2589630

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR AXLE <i>Free</i>	1	3605.60	+ 3,605.60
REAR LH BEARING	1	477.60	+ 477.60
REAR LH DOOR <i>Pyro</i>	1	2865.70	+ 2,865.70
REAR LH DOOR RAIL	1	507.00	+ 507.00
REAR LH DOOR RAIL END GARNISH	1	265.00	+ 265.00
REAR LH FENDER <i>Dented</i>	1	2385.60	+ 2,385.60
REAR LH FENDER AIR VENT	1	97.00	+ 97.00
REAR LH FENDER INNER PANEL	1	977.00	+ 977.00
REAR LH FENDER INNER TRIM BOARD	1	489.50	+ 489.50
REAR LH METAL RIM	1	453.50	+ 453.50
Subtotal before discount			12,123.50
Percentage discount 25%			3,030.88
Sub-total 1			9,092.63
REAR LH FENDER INNER TRIM BOARD CLIPS - SET <i>Abel M</i>	1	50.00	X 50.00
Subtotal before discount			50.00
Percentage discount 0%			0.00
Sub-total 2			50.00
Parts-total			9,142.63

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

I-DEAL AUTO TRADING PRIVATE LIMITED
18 SIN MING LANE #03-06 MIDVIEW CITY
SINGAPORE 573960

Contact : 87789969 98191208

TAX INVOICE

Repair Code : CLM18312

Date in : 14/12/2024

Vehicle Num. : GBE6288Y

Model : TOYOTA HIACE VAN TURBO 5 DR MANUAL

Chassis/Eng# : JTFHT02P400189974/1KD2589630

LABOUR

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.	450.00
To road test driving, check and resetting wheel alignments system.	100.00
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	80.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,200.00
To apply anti-rust chemical on repaired and replaced panel.	100.00
Labour Total	2,930.00
Parts & Labour Total	12,072.63

*** This is a computer-generated document which requires no signature. ***

page 2

Adrian Lj
1/5 16/12/24.

03 Rys.

Total: 2227.50

1/5 1.7K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: