

Vehicle Estimate

Supplier: _____

Customer: _____

DETAIL LAB	
Person-in-charge:	
Chassis No.:	
Year:	

Our Ref: INV

Vehicle No.:

SUB 5539C

Make & Model:

Toyota Harrier.
(white)

Car In Date & Mileage: _____

Car Out Date & Mileage: _____

Pg 1/2

No.	Parts/Description	Qty	Unit Price (\$)	
1	Rr Bumper Assy Cnt	1PC	1760.00	✓
2	Rr Left / Right Retainers .?	2PCS	110 x 2	?
3	Rr Bumper Lower Cover . Cnt	1PC	680.00	✓
4	LH tail lamp Panel HH	1PC	680.00	X
5	Rear End Panel Assy .HH	1PC	860.00	X
6	Rr LH Quarter Panel . HH	1PC	1560.00	X
7	LH tail lamp Outer HH	1PC	580.00	✓
8	LH tail lamp . Inner HH	1PC	540.00	✓
9	Tailgate HH	1PC	2200.00	X
10	Tailgate Lock Assy . HH	1PC	485.00	X
11	Wheel Bearing HH	1PC		X
12	Wheel Knuckle Assy HH	1PC		X
13	Rear Lower control Arm . HH	1PC		X
14	Rear LH Trailing Arm HH	1PC		X
15	Rear LH Shock Absorber HH	1PC		X
16				
17				
18	25% discount			
19				
20				
21				
22				
23	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
24				
25				
26				
27				
28				
29	Acknowledged by Repairer Signature: _____ Date: _____			
30				

Vehicle Estimate

Supplier: _____

Customer: _____

DETAIL LAB

Person-in-charge: _____

Chassis No.: _____

Year: _____

Car In Date & Mileage: _____

Car Out Date & Mileage: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Our Ref: INV

Vehicle No.:

8LB 5539 C .

Make & Model:

Toyota Hamier
(white) .

pg 2/2

No.	Parts/Description	Qty	Unit Price (\$)	
1	Reverse sensor set HM	1 set	400.00	X
2	Number plate set HM	1 set	40.00	X
3	Rt Bumper clips 3 fasteners HM	1 set	80.00	30/-
4	Tail Gate inner Panel clips HM	1 set	60.00	X
5	235/50 R19 Pirelli P-zero tyre end 60% dep	1 pc.	380.00	168/-
6	19" Sport Rim HM	1 pc.	1200.00	X
7				
8				
9				
10				
11				
12	Labour			
13	wheel Alignment		160.00	60/-
14	Removal/Installation Rear Under carriage		400.00	NM
15	Rim/Tyre Removal 3 Installation/Balancing		60.00	20/-
16	Panel Repair Affected Areas		900.00	400/-
17	Spray Painting Affected Areas		900.00	400/-
18	Water proofing to End Panel 3 NCC Panels		180.00	20/-
19	check wiring		90.00	NM
20	Paint Protection Coating (INV) ?		880.00	?
21				
22				
23	24/07/2024 @ 1600h			
24	Lt Andrew			
25	2/Save 4 dgs			
26				
27	LKK Auto			
28				
29				
30				