

KAI LIANG MOTOR SERVICE
BLK 1 KAKI BUKIT AVE 6 #01-101
AUTO BAY@KAKI BUKIT
S'PORE 417883 TEL: 67474189

Not Authorized
for
Morris
2/17/24
d/s \$1300/
2 days
Telephone. Akrept

VEHICLE No: YP 9023U

LIST ITEM

1PC	FRONT BUMPER	R	\$1,227.00 X
1PC	FRONT BUMPER PROTECTOR O/S	groth	\$369.81
1PC	FRONT SIDE LAMP O/S	one	\$187.50
1PC	FRONT SIGNAL LAMP O/S	310	\$288.21
1PC	HEADLAMP O/S	holder one	\$685.20
1PC	FRONT CORNER PANEL O/S	R	\$355.20 X
1PC	FRONT DOOR O/S	R	\$1,948.00 X
			\$5,060.92
			LESS 25% \$3,795.69

TO CHECK WIRING	\$50.00 20
TO SPRAY RUST PROOFING	17 \$50.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$500.00 280
TO PUTTY & SPRAY PAINTING	\$450.00 200
TOTAL	\$4,845.69

p. 153072
252
1148.04
500
1648.04
202
1318.42

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: