

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933
Reg : 201838521G

DATE : 22.07.2024

TO : **1ST CAP INSURANCE**
VEHICLE NO : **GBG 8234 D**
MODEL : **NISSAN CABSTAR**
DATE/TIME ACCIDENT : 07.07.2024 / 2040
DATE OF REG : 06.11.2017
CHASSIS : JN1SC2F24Z0860378

Hui Rong

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Del'd</i>	1	\$ 785.90	\$ 785.90
2	HEAD LAMP <i>Ren</i>	1	\$ 456.90	\$ 456.90
3	HEAD LAMP LOWER GARNISH <i>Ren</i>	1	\$ 125.60	\$ 125.60
4	SIDE MIRROR RH <i>Ren</i>	1	\$ 205.80	\$ 205.80
5	FRONT CORNER PANEL RH <i>Repair</i>	1	\$ 480.20	\$ 480.20
6	FRONT DOOR RH <i>Dented</i>	1	\$ 1,696.70	\$ 1,696.70
7	FRONT DOOR INNER TRIM RH <i>Ren</i>	1	\$ 785.60	\$ 785.60
8	FRONT DOOR HINGE RH <i>Ren</i>	2	\$ 78.60	\$ 157.20
9	FRONT DOOR WEATHER STRIP RH <i>Ren</i>	1	\$ 192.60	\$ 192.60
10	FRONT DOOR INNER LOCK <i>Ren</i>	1	\$ 186.50	\$ 186.50
11	FRONT DOOR LOCK CATCH <i>Ren</i>	1	\$ 41.20	\$ 41.20
12	FRONT DOOR SIGNAL LAMP RH <i>Could</i>	1	\$ 53.60	\$ 53.60
13	FRONT DOOR STEP GARNISH RH <i>Could</i>	1	\$ 186.30	\$ 186.30
14	FRONT DOOR STEP PANEL RH <i>Repair</i>	1	\$ 345.20	\$ 345.20
TOTAL PRICE				\$ 5,699.30
LESS 10%				\$ 569.93
SUB TOTAL PRICE				\$ 5,129.37

2475.80

2228.22

TO : **1ST CAP INSURANCE**
 VEHICLE NO : **GBG 8234 D**
 MODEL : **NISSAN CABSTAR**
 DATE/TIME ACCIDENT : 07.07.2024 / 2040
 DATE OF REG : 06.11.2017
 CHASSIS : JN1SC2F24Z0860378

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR COMPANY MARKER STICKER <i>mv</i>	1	\$ 35.00	\$ 35.00
TOTAL			\$	35.00

35

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 1,000.00	<i>400</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,000.00	<i>300</i>
3	TO SPRAY TUFF COAT	\$ 180.00	<i>30</i>
4	WIRING, BULB CHECKING ON HEADLAMP	\$ 120.00	<i>30</i>

760

TOTAL \$ 2,300.00

TOTAL PARTS COST : \$ 7,464.37
 TOTAL LABOUR COST : \$ 2,300.00
 TOTAL REPAIR COST : \$ 9,764.37

Adnan Ly
4/s 23/07/24.

03 Days
total: 3023.22

4/s: 2 HIC ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____