



## Final Report

Estimate No. : **b1 70581**  
Date Estimated : **22/07/2024**  
Prepared By : **Yap Mee Key**

Page No. :

**- ESTIMATE REPAIR FOR -**

**Ong Siew Khim**  
**158 Westwood Avenue**

**Singapore 648449**

**- ACCOUNT - 135**

**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	M LEAGE
SDV7288C	WBA62EG0505X47925	27/10/2023	X1 sDrive16i	11092

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper panel, trunk lid, rear bottom trim, rear bottom cover, rear RH trim, rear support include carrying out other necessary repairs caused by the accident	1,700.00		1,700.00
To respray trunk lid and rear bumper	2,076.00		2,076.00
To remove and install rear windscreen glass to facilitate repairs (For glass that are NOT shattered)	649.00		649.00
To conduct water leak tests	75.00		75.00
* To transfer lock mechanism from old to new trunk lid include conducting checks on new boot lid central locking system for proper function	531.00		531.00
** To supply Ceramic Coating ( See MCA's email )	300.00		300.00
To check electrical wiring system and lightings at the rear section for proper function	177.00		177.00
To remove old PDC assembly, replace damaged parts and reconnect to bumper include conducting checks for proper function	177.00		177.00
To carry out body cavity preservation (x1) (Per panel)	118.00		118.00
Sundries	150.00		150.00

**Performance Motors Limited.**

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269  
Co Reg No. 197401559W





## Final Report

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6	3.15	6.00	0.00	18.90
TRUNK LID	1,471.95	1.00	0.00	1,471.95
EXPANDING RIVET	0.50	20.00	0.00	10.00
REAR BUMPER PANEL PRIMED (M)	1,265.65	1.00	0.00	1,265.65
REAR BUMPER BOTTOM TRIM (M)	207.70	1.00	0.00	207.70
REAR BUMPER BOTTOM COVER (M)	364.35	1.00	0.00	364.35
REAR BUMPER RH TRIM (M)	53.70	1.00	0.00	53.70
REAR SUPPORT	534.50	1.00	0.00	534.50
EMBLEM GROMMET	1.00	2.00	0.00	2.00
LETTERING S DRIVE 16I	68.90	1.00	0.00	68.90
PLAQUE 74MM	76.55	1.00	0.00	76.55

### # SUPPLEMENTARY ITEMS

Total Labour :	5,953.00
Total Parts :	4,074.20
Total Labour & Parts (before GST) :	10,027.20
Deduction for Excess :	
Total Repair Costs less Excess:	10,027.20
GST @9%:	902.45
Grand Total :	10,929.65

**Performance Motors Limited.**

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

