

Attn Kenneth

19/08/2024 12:48

RECEIVED 01/01/2015 04:01  
67557713

67552687  
CHENGHOE VS

CHENG HOE WL

PAGE 01

## Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 769761  
TEL: 67556142 (YIS) FAX: 67557713 (YIS) Email: chm@chmnet.com.sg  
GST: 201001158E RCB NO: 201001153E

GZ2436T  
TP/A1G

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
TEL: 64193000 FAX: 64153727  
ATTN: Motor Claim Department

Estimate No: ES2400697/WS  
Date: 19 Aug 2024  
Policy No: 5142492729  
Veh Reg No: GZ2436T  
Make/Model: TOYOTA TOYOTA  
DYNA 150D  
Chassis No: JTFUR34Y303011520  
Engine No: 5L5633649  
Reg. Date: 03/02/2006

WS Ref: TP/AIG  
Claim Type: Third Party  
Accident Date: 21/07/2024  
TP Veh Reg No: SNH805L

### Estimate Repair Cost to Vehicle No: GZ2436T

| Description                                                                                                                        | U/Price  | Quantity | List Price           | Amount       |
|------------------------------------------------------------------------------------------------------------------------------------|----------|----------|----------------------|--------------|
|                                                                                                                                    |          |          | S\$                  | S\$          |
| List Price                                                                                                                         |          |          |                      |              |
| 1 FRONT BUMPER                                                                                                                     | 732.30   | 1 PC     | 732.30               | ✓            |
| 2 RH HEADLAMP                                                                                                                      | 1,240.10 | 1 PC     | 1,240.10             | ✓            |
| 3 FRONT RH DOOR                                                                                                                    | 2,681.60 | 1 PC     | 2,681.60             | ✓            |
| 4 FRONT RH DOOR BOTTOM HINGE                                                                                                       | 149.50   | 1 PC     | 149.50               | ✓            |
| 5 FRONT RH STEP TRAY LOWER GARNISH                                                                                                 | 411.10   | 1 PC     | 411.10               | ✓            |
| 6 FRONT RH CORNAL PANEL                                                                                                            | 483.40   | 1 PC     | 483.40               | ✓            |
|                                                                                                                                    |          |          | 5,098.00             |              |
|                                                                                                                                    | Less 25% |          | 1,424.50             | 4,273.50     |
| Special Net                                                                                                                        |          |          |                      |              |
| 7 FRONT RH DOOR COMPANY STICKER                                                                                                    | 20.00    | 1 PC     | 20.00                | ✓            |
|                                                                                                                                    |          |          | 20.00                | 20.00        |
| Labour                                                                                                                             |          |          |                      |              |
| 8 TO REMOVE AND REFIX FRT BUMPER ASSY, HEADLAMP, FRT RH DOOR & ATTACHMENT; KNOCK AND REPAIR FRT RH W/S PILLAR AND RE-ALIGN TO SAME | 450.00   | 1 LA     | 450.00               | 4001         |
| 9 TO REMOVE, TRANSFER AND REFIX FRT RH DOOR GLASS                                                                                  | 60.00    | 1 LA     | 60.00                | ✓            |
| 10 TO PUTTY AND RESPRAY ON FRT RH DOOR, FRT BUMPER, FRT RH CORNAL PANEL, FRT RH W/S PILLAR                                         | 550.00   | 1 LA     | 550.00               | 5001         |
|                                                                                                                                    |          |          | 1,060.00             | 1,060.00     |
|                                                                                                                                    |          |          | Total                | S\$ 5,333.50 |
|                                                                                                                                    |          |          | Add GST @ 9%         | 481.82       |
|                                                                                                                                    |          |          | Total Amount Payable | S\$ 5,835.32 |

Not Authorized  
11 Aug 2024 4700h  
Penny Ate Rain  
9 days

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

parts 4273.50  
supp 675.08  
# 4948.58  
SN 20  
lab 160

# 5928.58

45 # 4700

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey motor after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items to be resurveyed and is subject to the insurance company

Acknowledged by  
Signature  
Date

# Cheng Hoe Motor Pte Ltd

Blk 1019, Vishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

GZ2436T  
Suppl.

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
TEL: 64193000 FAX: 64153727  
ATTN: Motor Claim Department

WS Ref: TP/AIG  
Claim Type: Third Party  
Accident Date: 21/07/2024  
TP Veh Reg No: SNH805L

Estimate No: ES2400697/WS  
Date: 20 Aug 2024  
Policy No: 5142492729  
Veh Reg No: GZ2436T  
Make/Model: TOYOTA TOYOTA  
DYNA 150 D  
Chassis No: JTFUF34Y303011520  
Engine No: 5L5633649  
Reg. Date: 03/02/2006

## Estimate Repair Cost to Vehicle No :GZ2436T

| Description           | U/Price | Quantity        | List Price | Amount     |
|-----------------------|---------|-----------------|------------|------------|
|                       |         |                 | S\$        | S\$        |
| Supplementary 1       |         |                 |            |            |
| List Price            |         |                 |            |            |
| 1 FRONT RH DOOR GLASS | 900.10  | 1 PC <i>mgm</i> | 900.10     | ✓          |
|                       |         |                 | 900.10     |            |
|                       |         | Less 25%        | 225.03     | 675.08     |
| Total                 |         |                 |            | S\$ 675.08 |
| GST Amount            |         |                 |            | S\$ 60.76  |
| Total Amount Payable  |         |                 |            | S\$ 735.83 |

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE