

19/08/2024 12:48

RECEIVED 01/01/2015 04:01
6755771367592667
CHENGHOE YS

CHENG HOE WL

PAGE 01

Cheng Hoe Motor Pte Ltd

Blk 1019, Vishnu Industrial Park A 401-374/382, Singapore 769761
 TEL: 67556142 (YIS) FAX: 67557713 (YIS) Email: chm@chmnet.com.sg
 GST: 201001158E RCB NO: 201001153E

GZ2436T
 TP/A1G

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

Estimate No: ES2400697/WS
 Date: 19 Aug 2024
 Policy No: 5142492729
 Veh Reg No: GZ2436T
 Make/Model: TOYOTA TOYOTA
 DYNIA 150D
 Chassis No: JTFUR34Y303011520
 Engine No: 5L5633649
 Reg. Date: 03/02/2006

WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 21/07/2024
 TP Veh Reg No: SNH805L

Estimate Repair Cost to Vehicle No: GZ2436T

PAGE: 1/1

Description	U/Price	Quantity	List Price	Amount
			SG	SG
List Price				
1 FRONT BUMPER	732.30	1 PC	732.30	✓
2 RH HEADLAMP	1,240.10	1 PC	1,240.10	✓
3 FRONT RH DOOR	2,681.60	1 PC	2,681.60	✓
4 FRONT RH DOOR BOTTOM HINGE	149.50	1 PC	149.50	✓
5 FRONT RH STEP TRAY LOWER GARNISH	411.10	1 PC	411.10	✓
6 FRONT RH CORNAL PANEL	483.40	1 PC	483.40	✓
			5,698.00	
	Less 25%		1,424.50	4,273.50
Special Net				
7 FRONT RH DOOR COMPANY STICKER	20.00	1 PC	20.00	✓
			20.00	20.00
Labour				
8 TO REMOVE AND REFIX FRT BUMPER ASSY, HEADLAMP, FRT RH DOOR & ATTACHMENT; KNOCK AND REPAIR FRT RH W/S PILLAR AND RE-ALIGN TO SAME	450.00	1 LA	450.00	✓
9 TO REMOVE, TRANSFER AND REFIX FRT RH DOOR GLASS	60.00	1 LA	60.00	✓
10 TO PUTTY AND RESPRAY ON FRT RH DOOR, FRT BUMPER, FRT RH CORNAL PANEL, FRT RH W/S PILLAR	550.00	1 LA	550.00	✓
			1,060.00	1,060.00
			Total	SG 5,333.50
			Add GST @ 9%	481.82
			Total Amount Payable	SG 5,835.32

Not Authorised
 11 Rm 3 4700p
 Repair After Pain
 4 days

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

parts 4273.50
 supp 675.08
 # 4948.58
 SN 20
 lab 960

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey motor after spray painting
- To dislodge damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items of the resurveyed and is subject to the insurance company

Acknowledged by:

Signature:

Date:

5928.58

45 # 4700p

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GZ2436T
Suppl.

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

Estimate No: ES2400697/WS
Date: 20 Aug 2024
Policy No: 5142492729
Veh Reg No: GZ2436T
Make/Model: TOYOTA TOYOTA
DYNA 150 D
Chassis No: JTFUF34Y303011520
Engine No: 5L5633649
Reg. Date: 03/02/2006

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 21/07/2024
TP Veh Reg No: SNH805L

Estimate Repair Cost to Vehicle No :GZ2436T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 FRONT RH DOOR GLASS	900.10	1 PC <i>mgm</i>	900.10 ✓	
			900.10	
		Less 25%	225.03	675.08
Total				S\$ 675.08
GST Amount				S\$ 60.76
Total Amount Payable				<u>S\$ 735.83</u>

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE