

Date: 23-7-2024

Vehicle No: SNR49A

Model: Tesla Model 3

Chassis: LRW3F7ELXMC283029

Reg.Year: 3.9.2021

Third Party Insurer: AIG

Third Party Veh No: SJJ121M

Date of Accident: 22/7/2024

Estimator: Loong

Surveyor:

*Not Notified
Returning After Paint
2 day,
@ 1933-99*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1	mg cm	RE \$766.00
2	REAR BUMPER LOWER	1	mg cm	RE \$140.18
3	REAR BUMPER CENTER BRACKET	1		CR \$52.33
4	REAR BUMPER REINFORCEMENT	1		BR \$271.02
5	REAR REVERSE SENSOR	1	\$163.55	RE \$490.65
6	REAR REVERSE SENSOR MOUNTING BRACKET	6	ME \$4.67	\$28.02
SUB TOTAL				\$1,748.20
LESS 10%				-\$174.82
PARTS TOTAL				\$1,573.38

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		ME \$55.00
2	REAR BUMPER LOWER CLIPS	1		ME \$50.00
3	TO RE-COAT OF REAR BUMPER	1		ME \$130.00
S/N TOTAL				\$235.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$450.00 1801

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, ETC

\$350.00 2201

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$100.00 601

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$80.00 101

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LABOUR TOTAL \$980.00

TOTAL \$2,788.38

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

8A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011

