

AUTOBAY

AutoBay Pte Ltd UEN: 200909070G
 1 Kaki Bukit Avenue 6 #02-11
 AutoBay @ Kaki Bukit Singapore 417883
 T. 8618 6116 F. 6636 5355

NOT Authorized
 all
 moras
 25/7/24
 4 days
 2700/
 Alaphat Ate 127~

Regn No : SKH864B

Make & Model : Mercedes Benz C180

ITEM NO	DESCRIPTION OF ITEMS	QUANTITY (Piece/Set)	UNIT PRICE (S\$)	AMOUNT (S\$)
<u>Nett Items:</u>				
1	Rear bumper <i>cut/Torn</i>	1	\$ 2,094.00	\$ 2,094.00
2	Rear bumper side retainer <i>11</i>	2	\$ 88.00	\$ 176.00
3	Rear fender RH <i>R</i>	1	\$ 2,185.00	\$ 2,185.00
4	Rear fender innershield RH <i>11</i>	1	\$ 186.00	\$ 186.00
5	Rear wheel rim RH <i>cut/warped</i>	1	\$ 1,850.00	\$ 1,850.00
6	Rear wheel hub with bearing RH <i>11</i>	1	\$ 316.00	\$ 316.00
7	Rear wheel bearing RH <i>11</i>	1	\$ 115.00	\$ 115.00
8	Rear shock absorber RH <i>11</i>	1	\$ 520.00	\$ 520.00
9	Rear knuckle arm RH <i>11</i>	1	\$ 1,265.00	\$ 1,265.00
10	Rear control arm RH <i>11</i>	1	\$ 530.00	\$ 530.00
11	Rear lower arm RH <i>11</i>	1	\$ 520.00	\$ 520.00
12	Rear stay arm RH <i>11</i>	1	\$ 608.00	\$ 608.00
13	Rear trailing arm RH <i>11</i>	1	\$ 435.00	\$ 435.00
14	Rear trailing arm RH lower cover <i>11</i>	1	\$ 440.00	\$ 440.00
15	Rear drive shaft RH <i>11</i>	1	\$ 135.00	\$ 135.00
16	Rocker panel RH <i>11</i>	1	\$ 2,329.00	\$ 2,329.00
17	Rocker panel outer garnish RH <i>11</i>	1	\$ 655.00	\$ 655.00
18	Rear door RH <i>R</i>	1	\$ 2,235.00	\$ 2,235.00
19	Rear door chrome moulding RH <i>11</i>	1	\$ 175.00	\$ 175.00
20	Rear door weatherstrip RH <i>11</i>	1	\$ 280.00	\$ 280.00
			Sub-total	\$ 17,049.00
			Less 10.00%	\$ 1,704.90
			List Items Total	\$ 15,344.10

<u>Special Nett Items:</u>				
1	Rear bumper clip (1 set) <i>11</i>	1	\$80.00	\$ 80.00
2	Rear fender innershield clip (1 set) <i>11</i>	1	\$60.00	\$ 60.00
3	Rear tyre RH <i>80</i>	1	\$400.00	\$ 400.00
			S/Nett Items Total	\$ 540.00

<u>Labour Charge Items:</u>				
1	To check electrical wiring systems		\$ 80.00	20
2	To conduct computerized wheel alignment		\$ 160.00	60
3	To diagnose, erase fault memory code after repair		\$ 11 180.00	X
4	To remove, refit and transfer all door fittings to new door		\$ 11 180.00	X
5	To apply undercoating		\$ 11 100.00	X
6	To respray painting & etc		\$ 1,500.00	400
7	Panel beating, cut, weld, remove and replacing above parts		\$ 1,200.00	600
			Labour Charge Total	\$ 3,400.00

Overall Estimate Parts & Labour

Grand total \$ 19,284.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Hidden, inaccessible damage parts shall be submitted through supplementary

P- 1741.01
 102
 P- 156691
 S.N 730
 L- 1080
 337691
 202
 2701