



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO QY 120D

| REPLACEMENT OF PARTS |                                     |             |                        |                   |
|----------------------|-------------------------------------|-------------|------------------------|-------------------|
| Qty                  | Description of Parts                | Condition   | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1                    | FRONT BUMPER                        | CRACKED     | \$960.00               | \$718.00          |
| 1                    | FRONT BUMPER LOWER GRILLE           | CRACKED     | \$1,032.00             | \$826.00          |
| 1                    | LOWER GRILLE CHROME GARNISH         | DENTED      | \$280.00               | \$280.00          |
| 1                    | FRONT BUMPER LOWER GARNISH          | DENTED      | \$260.00               | \$260.00          |
| 1                    | FRONT BUMPER TOW COVER              | SERVICEABLE | \$70.00                | \$0.00            |
| 1                    | FRONT BUMPER NO PLATE BASE          | CRACKED     | \$250.00               | \$250.00          |
| 1                    | RHF FOG LAMP COVER                  | DENTED      | \$215.00               | \$215.00          |
| 1                    | FRONT PARKING SENSOR                | SERVICEABLE | \$360.00               | \$0.00            |
|                      | <b>LESS 20.00 / 25.00% DISCOUNT</b> |             | (\$685.40)             | (\$637.25)        |
|                      |                                     |             | <b>\$2,741.60</b>      | <b>\$1,911.75</b> |

| Special Nett |                                |           |                        |                   |
|--------------|--------------------------------|-----------|------------------------|-------------------|
| Qty          | Description of Parts           | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1            | SET NUMBER PLATE + CASING (SN) | BENT      | \$50.00                | \$45.00           |
|              |                                |           | <b>\$50.00</b>         | <b>\$45.00</b>    |

| Labour |                                                                  |           |                        |                   |
|--------|------------------------------------------------------------------|-----------|------------------------|-------------------|
|        | Description of Parts                                             | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
|        | TO REPAIR & REMOVE/REPLACE PARTS @ PORTIONS AFFECTED BY ACCIDENT |           | \$600.00               | \$200.00          |
|        | TO PREP, PAINT AND FINISH PORTIONS AFFECTED BY ACCIDENT          |           | \$500.00               | \$220.00          |
|        | REMOVE & REPLACE SENSORS                                         |           | \$150.00               | \$60.00           |
|        | CHECK ELECTRICAL WIRING                                          |           | \$30.00                | \$15.00           |
|        |                                                                  |           | <b>\$1,280.00</b>      | <b>\$495.00</b>   |

| GRAND TOTAL |                             |  | <b>\$4,071.60</b> | <b>\$2,451.75</b> |
|-------------|-----------------------------|--|-------------------|-------------------|
|             | RECOMMENDED COST OF REPAIRS |  |                   | <b>\$2,451.75</b> |
|             | LESS EXCESS                 |  |                   | <b>(\$350.00)</b> |
|             | NETT LIABILITY              |  |                   | <b>\$2,101.75</b> |

Report Ref No: CS/FCI24070376/Kvp3e2

MARKET VALUE: \$45,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$34,711.00=NETT VALUE: \$10,289.00



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## **KSC**

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.