



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO QY 120D

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	CRACKED	\$960.00	\$718.00
1	FRONT BUMPER LOWER GRILLE	CRACKED	\$1,032.00	\$826.00
1	LOWER GRILLE CHROME GARNISH	DENTED	\$280.00	\$280.00
1	FRONT BUMPER LOWER GARNISH	DENTED	\$260.00	\$260.00
1	FRONT BUMPER TOW COVER	SERVICEABLE	\$70.00	\$0.00
1	FRONT BUMPER NO PLATE BASE	CRACKED	\$250.00	\$250.00
1	RHF FOG LAMP COVER	DENTED	\$215.00	\$215.00
1	FRONT PARKING SENSOR	SERVICEABLE	\$360.00	\$0.00
	LESS 20.00 / 25.00% DISCOUNT		(\$685.40)	(\$637.25)
			\$2,741.60	\$1,911.75

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET NUMBER PLATE + CASING (SN)	BENT	\$50.00	\$45.00
			\$50.00	\$45.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REPAIR & REMOVE/REPLACE PARTS @ PORTIONS AFFECTED BY ACCIDENT		\$600.00	\$200.00
	TO PREP, PAINT AND FINISH PORTIONS AFFECTED BY ACCIDENT		\$500.00	\$220.00
	REMOVE & REPLACE SENSORS		\$150.00	\$60.00
	CHECK ELECTRICAL WIRING		\$30.00	\$15.00
			\$1,280.00	\$495.00

GRAND TOTAL		\$4,071.60	\$2,451.75
	RECOMMENDED COST OF REPAIRS		\$2,451.75
Report Ref No: CS/FCI24070376/Kvp3e2			

MARKET VALUE: \$45,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$34,711.00=NETT VALUE: \$10,289.00

KSC

KENNETH KONG SENG CHEONG



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.