

## ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : OD

Ins Company : MS First Capital

Excess : \_\_\_\_\_

Date of Accident : 19.07.24

Suggested Days of Repair : 5

### Repair Estimates

Parts (a) Cost / List Price Items	\$ 3,427.00
Plus/Less <u>25%</u>	\$ 685.40
Total of Cost / List	\$ 2,741.60
(b) Nett Price Items	\$ -
Less _____	_____
Total of Nett Item	_____
(c) Special Nett Items	\$ 50.00
Total Parts Cost (Appendix A)	\$ 2,791.60
Labour (Appendix B)	\$ 1,100.00
Total Repair Cost	\$ 3,891.60

The above total will be subjected to 8% G.S.T.

Vehicle No. : QY120D

Make & Model : Toyota Camry

Year of Manufacture : 2016

Chassis No. : MR053CK5004020285

Engine No. : 2ARU335565

Policy No. : D-24102282MFQC/2

Time of Accident : 1030

In-house Vehicle Assessor

Case Owner : \_\_\_\_\_

Signature : \_\_\_\_\_

Contact No  
**Operation**  
KELVIN SU  
TEL: 9786 4236  
E: [kelvinsukwen@cdge.com.sg](mailto:kelvinsukwen@cdge.com.sg)

JOHARI  
TEL: 972103705  
E: [ioharibh@sparkcarcare.com](mailto:ioharibh@sparkcarcare.com)

SUN PIN  
TEL: 9728 8916  
E: [oisunpin@cdge.com.sg](mailto:oisunpin@cdge.com.sg)

*Not Authorized  
Repairing Blipaim  
@ 2451.75*

Name of Surveyor : Kennerth  
Company : LICK  
Survey conducted on : 24/7/24 at \_\_\_\_\_

### Remarks By Surveyor

(a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : ☒ Required / Not Required

(d) Excess : \$ TBA

(e) Signature of surveyor : Le

Date: 24/7/24

### Spare Parts

Vehicle No : QY120D Case Owner : 0  
Make & Model : Toyota Camry Year Manufactur : 2016  
Chassis No : MR053CK5004020285 Engine No : 2ARU335565  
Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_  
Order By : \_\_\_\_\_ Type of Claim : OD

No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front Bumper <i>718</i>		<i>CM</i>	\$ 960.00			<i>✓</i>
2	Front Bumper Lower Grille <i>826</i>		<i>CM</i>	\$ 1,032.00			<i>✓</i>
3	Lower Grille Chrome Garnish		<i>RU</i>	\$ 280.00			<i>✓</i>
4	Front Bumper Lower Garnish		<i>RU</i>	\$ 260.00			<i>✓</i>
5	Front Bumper Tow Cover		<i>SN</i>	\$ 70.00			<i>X</i>
6	Front Bmper No Plate Base		<i>CM</i>	\$ 250.00			<i>✓</i>
7	RHF Fog Lamp Cover		<i>RU</i>	\$ 215.00			<i>✓</i>
8	Front Parking Sensor			\$ 360.00		<i>SN</i>	<i>X</i>
9	Number plate + casing set				<i>R</i> \$ 50.00		<i>45 SN</i>
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## Labour

Vehicle No. : QY120D  
Make & Model : Toyota Camry

Case Owner : \_\_\_\_\_ 0 \_\_\_\_\_

Year of Manufacture : \_\_\_\_\_ 2016 \_\_\_\_\_

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.