· H-LIU

antity

COMPORTUELGRO ENGINEERING PTELTU 205 BRADDELL ROAD SINGAPORE 579701

TEL: 63837466/7730/7656/7362 FAX: 62815767

ACCIDENT REPAIR ESTIMATES Our Ref: **QY120D** Vehicle No. OD Type of Claim: **Toyota Camry** Make & Model 2016 Year of Manufacture MR053CK5004020285 Chassis No. 2ARU335565 **MS First Capital** Engine No. Ins Company Policy No. D-24102282MFQC/2 Excess 19.07.24 1030 Time of Accident Date of Accident : Suggested Days of Repair : _____ In-house Vehicle Assessor Case Owner **Repair Estimates** Signature Parts (a) Cost / List Price Items Contact No Plus/Less 685.40 Operation **KELVIN SU** Total of Cost / List 2,741.60 TEL: 9786 4236 E: kelvinsukwen@cdge.com.sg (b) Nett Price Items \$ -**JOHARI** Less TEL: 972103705 E: joharibh@sparkcarcare.com Total of Nett Item **SUN PIN** 50.00 TEL: 9728 8916 (c) Special Nett Items E: oisunpin@cdge.com.sg Nor Norhain Runny Bapain 2,791.60 Total Parts Cost (Appendix A) 1,100.00 Labour (Appendix B) 3,891.60 **Total Repair Cost** The above total will be subjected to 8% G.S.T. Name of Surveyor Company Survey conducted on Remarks By Surveyor (a) The repair of this vehicle is authorized / is not authorized until further notice. 02 day(s) (b) Recommended Days of Repair : Required / Not Required (c) Resurvey

Date: 24/7/29

(d) Excess

(e) Signature of surveyor

TEL: 63837466/7730/7656/7362 FAX: 62815767

Spare Parts

Vehicle No	: QY120D	Case Owner : 0
Make & Model	: Toyota Camry	Year Manufactur : 2016
Chassis No	: MR053CK5004020285	Engine No : 2ARU335565
Sales Order	:	Supplier :
Order By		Type of Claim : OD

No	Part Description	QTY	Cost Price	Li	st Price	Nett Price		S/N	'	Disposition By Surveyor
1	Front Bumper		cm	\$	960.00					<u></u>
12B	Front Bumper Lower Grille		cm	\$	1,032.00					_
3	Lower Grille Chrome Garnish	Pi	Py	\$	280.00					
4	Front Bumper Lower Garnish	Y .	01	\$	260.00					
5	Front Bumper Tow Cover	Sec	sn	\$	70.00					X
	Front Bmper No Plate Base	W	cm	10,2007	250.00					
	RHF Fog Lamp Cover	Now.	Dul	\$	215.00					
	Front Parking Sensor			\$	360.00					7
	Number plate + casing set		- 7	<u> </u>	1 1	<i>y</i>	B	\$	50.00	451N
	Number place + Casing Set					3.5	4			
10	AND COMPANY AND AND THE PROPERTY OF THE PROPER	- 1-5	759	\vdash			+		1.0	
11		- 10	4	 	-	-	\dashv			
12				\vdash		1.7	\dashv			1
13	Charles and the same of the sa			<u> </u>		100 000	\dashv		1 1	- Draftson M
14	The second secon		LKK Auto Consu			у	4			04.5. 4 1 5907
15	and the same of th		the Repairer of	he fo	llowing:		$\perp \! \! \! \! \! \perp$			300
6			To display damage							
			Parts prices are s				T			
+			 Third party survey 	y is on	a "Without Pre	judice" basis	+			
В		-++	No illugal modifie				+	\vdash		
)		-	 Supplementary its subject to final 	em(s)	must be resurv	nce Company	+	+		
			3 SUUJUCE TO IIII AI	PPIO			\bot	1		
			Acknowledged by F	Repair	er		\bot			
	To \$600 to		Signature:		5000 . 3.9	Train K. I				
+	of Tarini, while is objected.		Date:				士			
+-				一				+		
_				+-			4.	+-		_
			171	4				4		
				\top				\top		
			+	+		+		+		
				+		-		+		
	i i		<u>L</u>							146
				\top						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge vill be charged accordingly under supplementary.