

7/24/24, 3:37 PM

Repairer Estimates

Century Motors (Singapore) Pte Ltd (Co.Reg.No:192800002R)

6 Marsiling Lane,
Singapore 739145

Tel: 31572626 Email: claims@autoinsure.com.sg

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMB1SNW00016612305	Date of Loss:	17/07/2024
Vehicle Reg. No.:	PC5067U	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	JIANG KEVIN TRANSPORTATION SERVICES		

Make/Model:	ISUZU LT434P 7.8 SMT, 7.8 D (M)	Vehicle Reg. Date:	25/06/2015
Vehicle Colour:	MULTI-COLOUR		
Engine No:	6HK1663725	Chassis No:	JALLT434PE7000095
Odometer:	525031 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) 30

Present Location: CENTURY MOTORS (SINGAPORE) PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	58,385.00
Miscellaneous Items	666.00
Labour	6,350.00
Paintwork Labour	1,000.00
Towing	0.00

Gross Total (S\$)	66,401.00
+ GST 9.00% (S\$)	5,976.09
Nett Amount (S\$)	72,377.09

This claim is handled by: LOH CHEN KHUAN

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Tan Jiah 97495749/62863561
Not Authorise Ex: f69
25/7/24 @ 1030
L/S Resurvey after repair
Tan Jiah C1khuan@autoinsure.com
30 days.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 24 Jul 2024)
 Parts: N/A ISUZU LT434P 7.8 SMT 7.8 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Century Motors (Singapore) Pte Ltd/PC5067U/24/07/2024 15:37
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
 END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT WINDSCREEN LOWER	0.00	0.00	*6,200.00 F <i>era</i>
2	1		*FRT WINDSCREEN RUBBER MOULDING	0.00	0.00	*850.00 F <i>rec</i>
3	1		*FRT UPPER WINDSCREEN	0.00	0.00	*3,600.00 F <i>era</i>
4	1		*FRT UPPER WINDSCREEN INNER SEAL	0.00	0.00	*450.00 F <i>nd</i>
5	1		*FRT UPPER FRAME STRUCTURE	0.00	0.00	*2,900.00 F <i>bt</i>
6	1		*ROOF OUTER PANEL (FRT HALF PORTION)	0.00	0.00	*9,000.00 F <i>era</i>
7	1		*FRT PANEL	0.00	0.00	*4,200.00 F <i>era</i>
8	1		*FRT PANEL INNER STRUCTURE	0.00	0.00	*1,550.00 F <i>bt</i>
9	1		*FRT FACE STRUCTURE	0.00	0.00	*3,700.00 F <i>bt</i>
10	1		*FRT LH TOP LAMP	0.00	0.00	*250.00 F <i>era</i>
11	1		*WIPER LINKAGE <i>plus to</i>	0.00	0.00	*850.00 F <i>bt</i>
12	1		*FRT LH REAR VIEW MIRROR ASSY	0.00	0.00	*1,450.00 F <i>bro</i>
13	1		*FRT LH PILLAR BEAM INNER	0.00	0.00	*1,050.00 F <i>bt</i>
14	1		*FRT LH PILLAR OUTER	0.00	0.00	*1,200.00 F <i>bt</i>
15	1		*FRT DASHBOARD	0.00	0.00	*3,800.00 F <i>dis</i>
16	1		*FRT LH ENTRANCE DOOR	0.00	0.00	*2,250.00 F <i>bt</i>
17	1		*FRT LH STEP PANEL STRUCTURE	0.00	0.00	*1,400.00 F <i>Xnn</i>
18	1		*FRT LH ENTRANCE DOOR STEEL MOULDING	0.00	0.00	*980.00 F <i>de</i>
19	1		*FRT CENTER WINDSCREEN CASING GUARD	0.00	0.00	*1,300.00 F <i>cut</i>
20	1		*FRT LH LINKAGE	0.00	0.00	*1,300.00 F <i>bt</i>
21	1		*FRT VENTER INTERIOR PARTITION	0.00	0.00	*2,200.00 F <i>dis</i>
22	1		*FRT BUMPER	0.00	0.00	*2,250.00 F <i>cut</i>
23	1		*FRT BUMPER INNER STRUCTURE	0.00	0.00	*950.00 F <i>bt</i>
24	1		*FRT BUMPER LH BRACKET	0.00	0.00	*380.00 F <i>bt</i>
25	1		*FRT BUMPER FOG LAMP LH	0.00	0.00	*285.00 F <i>Xnn</i>
26	1		*FRT LH WIPER BLADE	0.00	0.00	*85.00 F <i>bt</i>
27	1		*FRT RH WIPER BLADE	0.00	0.00	*85.00 F <i>bt</i>
28	1		*FRT LH WIPER ARM HUB COVER	0.00	0.00	*115.00 F <i>dis</i>
29	1		*FRT RH WIPER ARM HUB COVER	0.00	0.00	*115.00 F <i>Xnn</i>
30	1		*FRT RH WIPER ARM	0.00	0.00	*155.00 F <i>Xnn</i>
31	1		*FRT LH WIPER ARM	0.00	0.00	*155.00 F <i>bt</i>
32	1		*FRT LH HEAD LAMP	0.00	0.00	*1,750.00 F <i>cut</i>
33	1		*FRT GRILLE	0.00	0.00	*980.00 F <i>cut</i>
34	1		*FRT GRILLE CHROME GARNISH	0.00	0.00	*370.00 F <i>Xnn</i>
35	1		*FRT GRILLE INNER STRUCTURE	0.00	0.00	*230.00 F <i>Xnn</i>
Total Parts (S\$)						58,385.00

F=Franchise part.

Century Motors (Singapore) Pte Ltd/PC5067U/24/07/2024 15:37. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

55830

10% 50247

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	ERP bracket	26.00
2	1	FRT NUMBER PLATE	40.00 30
3	1	SEALANT	600.00 450
Sub Total (S\$)			666.00

506

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAY PAINTING MULTI COLOR & DESIGN	New	1,000.00 ✓
<u>Labour Items</u>			
2	CHECK WIRING	New	100.00 50
3	LABOUR CHARGES TO REMOVE & REFIT FRT LOWER WINDSCREEN	New	1,000.00 800
4	LABOUR CHARGES TO REMOVE & REFIT FRT UPPER WINDSCREEN	New	1,000.00 800
5	LABOUR CHARGES TO REMOVE & REFIT DASHBAORD TO ASSIST REPAIR	New	350.00 ✓
6	LABOUR CHARGES TO REMOVE & REFIT INTERIOR LH TRIMS,CENTER PARTITION,UPHOLSTERY ETC TO ASSIST REPAIR	New	600.00 500
7	LABOUR CHARGES TO TRANSFER ENTRANCE DOOR FITTINGS TO ASSIST REPAIR	New	300.00 ✓
8	LABOUR CHARGES	New	3,000.00
Gross Labour Cost (S\$)			6500 7,350.00

2700

Century Motors (Singapore) Pte Ltd/PC5067U/24/07/2024 15:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

55830

506

6500

57253

2% - 45,802.40

Repair limit \$ 30,000

L/S \$ 30,000

30 days

*