



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070379/Dvp3m4
16 RAFFLES QUAY	Date:	05/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7382R	Veh. Inspected	SHD 6559A
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24006443MFCT	Excess	\$0.00
Assign From	HARMINDER KAUR	Assign Date	24/07/2024

### 2. Vehicle Details

Make & Model	TOYOTA PRIUS	C.C	1798
Engine No.	2ZR2G06929	Year of Reg.	13/12/2019
Chassis No.	JTDKB3FU503090355	Colour	BLUE
Odometer	407903 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	WEST LAKE	5
L/H Front Tyre	195/65R15	WEST LAKE	5
R/H Rear Tyre	195/65R15	WEST LAKE	5
L/H Rear Tyre	195/65R15	WEST LAKE	5

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	23/07/2024	Inspection Date	25/07/2024
Survey held at	BIFROST AUTO PTE LTD - 59 LOYANG DRIVE LEVEL 4 ROOM 7 SINGAPORE 508969		

### 5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days