

Accident Repair Estimate

ACCIDENT DATE: 17-Jul-24
 ACCIDENT TIME: 0536HRS
 ACCIDENT REPORT NUMBER: AR-2024-3861
 3RD PARTY CLAIM AGAINST: PC5067U

BUS NUMBER: SB586592
 BUS MODEL: WSD
 DATE OF SURVEY: 25-Jul-24

PARTS & MATERIAL COST

SECTION A:

Part or Item Description	Quantity	Total Cost
REAR WINDSCREEN SN C&D <i>bro</i>	1	\$170.00 ✓
REAR DOOR/F/GLASS C+ C+ SERIES <i>CR</i>	1	\$523.00 ✓
BUMPER REAR F/G C&D SERIES <i>CR</i>	1	\$305.00 ✓
RR LAMP PANEL O/S <i>CR</i>	2	\$162.00 ✓
LED TAILSTOP LAMP <i>CR</i>	1	\$194.40 ✓
LED INDICATOR LAMP <i>CR</i>	1	\$102.20 ✓
LED REVERSE LAMP <i>CR</i>	1	\$105.60 ✓
REFLEX REFLECTOR <i>MIS</i>	1	\$1.35 ✓
STRK SBS TRANSIT RR SD/DD <i>CR</i>	1	\$6.00 ✓
SIDE PANEL JR-KR O/S SIDE PANEL ASSY <i>BT</i>	1	\$250.00 ✓
REAR FRAME PILLAR/RR FRAME <i>BT</i>	1	\$153.00 ✓
ATTACHMENT BRACKET BOTTOM-RR FRAME <i>BT</i>	1	\$57.14 ✓
SKID SHOE @ K-RR FRAME <i>CR</i>	1	\$56.70 ✓
VERTICAL PILLAR @ KL-KR/SIDE FRAME <i>BT</i>	1	\$228.60 ✓
GAS JACK 0400N:RR ENG DOOR <i>BT</i>	2	\$52.00 ✓
LIMIT SWITCH-HYD PMP <i>CR</i>	1	\$23.13 ✓
FLUID RESERVOIR-HYD PMP <i>CR</i>	1	\$180.49 ✓
COMPARTMENT HINGE LHS 1 @ HL <i>BT</i>	1	\$122.10 ✓
COMPARTMENT HINGE RHS 1 @ JL <i>BT</i>	1	\$122.10 ✓
DOOR FRAME JR-KR O/S ALUM/A/B/C SERIES <i>2.5L</i>	1	\$163.80 ✓
INSULATION 01:CPSS25:25MMX1MX2M:WIRING <i>2.6L</i>	1	\$149.13 ✓
INSULATION HOLDER 01:1.0MM ALUM SHEET IN <i>2.6L</i>	1	\$33.42 ✓
ALUM WIRE MESH:ENG DR:1PC-1.8M IN <i>2.6L</i>	1	\$172.60 ✓
TOTAL PARTS & MATERIAL COST	1	\$3,333.76

ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)

SECTION B:

Assessment of Bus (With Damaged)	✓	\$188.00 ✓
To Remove / Replace / Repair Damaged Parts by Contractor	✓	\$3,800.00 ✓
To Remove / Replace / Repair Damaged Advertisement Panel		\$0.00
TOTAL LABOUR COST		\$3,988.00

SUMMARY

Total Repair Costs		\$7,321.76
Total Downtime (Days)	5	\$2,040.50
Towing Cost		\$0.00
Total Overheads Costs		\$2,196.53
TOTAL COST		\$11,558.79

*Please kindly note that the downtime (days) is just an estimate.
 *Please underwrite to acknowledge this repair estimate.

Prepared by: *ERIC NG* Surveyor Name & Contact: *Rasul-Hp 90010068*
Snr Technical Officer
Ulu Pandan Workshop
Bus Engineering

Signature: *as/ps* Signature: *as/ps*
 Date: *25/7/24* Date: *25/7/24*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accident Repair Estimate

ACCIDENT DATE: 17-Jul-24
 ACCIDENT TIME: 0536Hrs
 ACCIDENT REPORT NUMBER: AR-2024-3861
 3RD PARTY CLAIM AGAINST: PCS067U

BUS NUMBER: SBS8659Z
 BUS MODEL: WSD
 DATE OF SURVEY: 25-Jul-24

SECTION A: PARTS & MATERIAL COST			
Part or Item Description	Quantity	Total Cost	
REAR WINDSCREEN..SN C&D	1	\$170.00	
REAR DOOR/F/GLASS/C & C+ SERIES	1	\$523.00	
BUMPER,REAR-F/G C&D SERIES	1	\$305.00	
RR LAMP PANEL,O/S	1	\$162.00	
LED TAIL/STOP LAMP	2	\$194.40	
LED INDICATOR LAMP	1	\$102.20	
LED REVERSE LAMP	1	\$105.60	
REFLEX REFLECTOR	1	\$1.35	
STKR SBS TRANSIT RR SD/DD	1	\$6.00	
SIDE PANEL JR-KR,O/S,SIDE PANEL ASSY	1	\$250.00	
REAR FRAME PILLAR;RR FRAME	1	\$153.00	
ATTACHMENT BRACKET BOTTOM;RR FRAME	1	\$57.14	
SKID SHOE @ K;RR FRAME	1	\$56.70	
VERTICAL PILLAR @ KL-KR;SIDE FRAME	1	\$228.60	
GAS JACK 0400N;RR ENG DOOR	2	\$52.00	
LIMIT SWITCH;ADJUSTABLE @ RR ENG DR	1	\$23.13	
FLUID RESERVOIR;HYD.PMP	1	\$180.49	
COMPARTMENT HINGE LHS 1@ HL	1	\$122.10	
COMPARTMENT HINGE RHS 1@ JL	1	\$122.10	
DOOR FRAME JR-KR,O/S;ALUM;A/B/C SERIES	1	\$163.80	
INSULATION 01;CPSS25;25MM/IXMX2M;WIRING	1	\$149.13	
INSULATION HOLDER 01;1.0MM ALUM SHEET N	1	\$33.42	
ALUM WIRE MESH;ENG DR;1PC=1.8M N	1	\$172.60	
TOTAL PARTS & MATERIAL COST	1	\$3,333.76	/

SECTION B: ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)	
Assessment of Bus (With Damaged)	\$188.00
To Remove / Replace / Repair Damaged Parts by Contractor	\$3,800.00
To Remove/ Replace/ Repair Damaged Advertisement Panel	\$0.00
TOTAL LABOUR COST	\$3,988.00

SECTION C: SUMMARY		
Total Repair Costs		\$7,321.76 /
Total Downtime (Days)	5	\$2,040.50 /
Towing Cost		\$158.00 /
Total Overheads Costs		\$2,196.53
TOTAL COST		\$11,716.79

*Please kindly note that the downtime (days) is just an estimate.
 *Please undersign to acknowledge this repair estimate.

Prepared by:  **ERIC NG**
 Signature: **Snr Technical Officer**
 Ulu Pandan Workshop
 Bus Engineering

Surveyor Name & Contact: _____
 Signature: _____
 Date: _____

7321.76
 158.00
 7479.76