

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	CRAWFORD & COM	MPANY INTERNATIONAL PL	Ref:	CS3/CWF24070383/Rqp3m4	
	NO.8 SHENTON WA	ΑΥ	Date:	13/08/2024	
	#03-01 AXA TOWER	R SINGAPORE 068811	Code:	CWF	
_		Dalias Bartinslass - E		-	
1.					
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	XE 2466R	
	Policy No.	GL000042	Coverage	0	
	Claim No.	1101858/G/TWC	Excess	\$0.00	
	Assign From	TAN WEE CHIAU	Assign Date	24/07/2024	
2. Vehicle Details					
	Make & Model	MITSUBISHI FUSO FV51SJD2DEA	C.C	11967	
	Engine No.	OM457LA457972C0330708	Year of Reg.	29/11/2016	
	Chassis No.	FV51SJA20123	Colour	WHITE	
	Odometer	485238 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	FAIR	
	Modification(s)	RIMS: NIL			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	315/80R22.5	MICHELIN	8	
	L/H Front Tyre	315/80R22.5	MICHELIN	8	
	R/H Rear Tyre	315/80R22.5 (D)	MICHELIN	8/8	
	L/H Rear Tyre	315/80R22.5 (D)	MICHELIN	8/8	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
5.	5. General Information				
	Accident Date	15/07/2024	Inspection Date	19/07/2024 (12:18)	
	Survey held at	SIM LEE CONSTRUCTION & TRANSPORT PTE LTD			
	7 SOON LEE STREET, #05-08, ISPACE,				
		#05-06, ISPACE, SINGAPORE 627608			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000-\$10,000					
5b. Estimate Days of Repair					

## MRB

## MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.