

MS CAR AUTO PTE LTD

8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @KAKI BUKIT
SINGAPORE 415875

TO	: AIG	DATE	23/7/2024
VEHICLE NO	: FZ616R (2021)		Yan
VEHICLE MODEL	: HONDA ADV750		
CHASSIS NO	: JH2RH10A9MK007982		

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	REAR MUDFLAP <i>ut</i>		135.00	✓
2	REAR SIGNAL LAMP @45 <i>new</i>		90.00	✗
3	REAR EXHAUST PIPE <i>Rpr</i>		780.00	✗
4	REAR EXHAUST PIPE HEAT SHIELD <i>ut</i>		185.00	✓
5	REAR SLIDER <i>ut</i>		145.00	✓
6	REAR FOOTREST <i>ut</i>		110.00	✓
7	BALANCER <i>ut</i>		85.00	✓
8	HAND LEVER PROTECTOR <i>cracked</i>		285.00	✓
9	SIDE FAIRING (RED) <i>Rpr</i>		390.00	✗
10	FRONT SIGNAL LAMP <i>cracked</i>		105.00	✓
11	FRONT WING MIRROR <i>ut</i>		90.00	✓
		Less	2400.00	
		10%	240.00	10%
			2160.00	
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE <i>new</i>		20.00	✗
2	GRASH BAR (GIVI) <i>ut</i>		700.00	500
		Total Parts	720.00	

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	LABOUR <i>A3J</i>	400.00	200
2	SPRAY PAINTING	400.00	150
3	WIRING	50.00	30
4	TO REMOVE REAR EXHAUST PIPE	150.00	50
	Labour Total :	1000.00	
	TOTAL (PARTS & LABOUR):	4856.50 3880	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

12/7

total: 1856

1/8: 151c

03 days